Models Title Category Last modified	SSM69558 XF / X250 XJ / X351 Navigation errors or freezing on the `Initalization` screen Electrical 19-Nov-2013 00:00:00 207000 Entertainment Systems
Content	Issue: A customer may report that when trying to access the Navigation system they have errors or the system freezes on the "Initializing" screen. Cause: Software compatibility issues Action: If a customer reports the concern detailed above an IAM software update will be required using SDD. To complete the update follow the instructions below: -Ensure DVD 135 patch 9 or later is loaded -Connect the vehicle to a suitable power supply -Connect SDD to the vehicle -Start a new diagnostic session -Enter symptoms: Electrical - Information and entertainment system - Entertainment System -From the "Extras" tab select "Configure existing module Audio front control module" -When complete end the session, and disconnect SDD. -Disconnect the power supply