



Service Bulletin

File in Section: -

Bulletin No.: PIP4112M

Date: August, 2013

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Sag Or Hesitation On Acceleration

Models: 2008-2013 Buick Enclave
 2013 Buick Encore
 2010-2013 Buick LaCrosse
 2011-2013 Buick Regal
 2012-2013 Buick Verano
 2006-2009 Cadillac STS-V, XLR, XLR-V
 2007-2013 Cadillac Escalade, Escalade EXT, Escalade ESV, SRX
 2007-2011 STS
 2008-2013 Cadillac CTS
 2013 Cadillac ATS, XTS
 2006-2013 Chevrolet Corvette
 2007-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
 2008-2013 Chevrolet Equinox, Malibu
 2009-2013 Chevrolet Traverse
 2010-2013 Chevrolet Camaro, Cruze, Express
 2012-2013 Chevrolet Impala, Orlando, Sonic
 2013 Chevrolet Trax
 2007-2013 GMC Sierra, Yukon, Yukon XL
 2008-2013 GMC Acadia
 2009-2013 GMC Terrain
 2010-2013 GMC Savana
 2007-2010 Pontiac G6
 2008-2009 Pontiac G8
 2008-2009 Pontiac Torrent
 2007-2009 Saturn Aura
 2008-2010 Saturn Outlook, Vue
 Equipped With a Gasoline Engine and Automatic Transmission

This PI was superseded to add the Chevrolet Orlando and Trax. Please discard PIP4112L.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a sag or hesitation when accelerating under the following conditions:

When coasting with a closed throttle and then aggressively applying the throttle. Examples of this maneuver include a rolling stop or a lane change maneuver. In this type of maneuver, even though the accelerator is applied aggressively, the throttle blade is opened slowly for up to 0.7 seconds to help minimize drive-line lash and clunking.

Also in a vehicle equipped with a six speed automatic transmission when making a hard, complete stop with a closed throttle, immediately followed by an aggressive throttle opening the transmission down-shifts may not be completed by the time the throttle is opened. As a result approximately 0.5 seconds of "zero" torque may be commanded to allow the shift to first gear to occur.

Recommendation/Instructions

Both of the above conditions are a result of Torque Management and both of these conditions should be considered normal and no repairs should be attempted.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.