



## Service Bulletin

File in Section: -

Bulletin No.: PIP4813B

Date: March, 2013

# PRELIMINARY INFORMATION

**Subject:** SES Light Rough Running And/Or Lack Of Power - Inspect Carbon Absorber

**Models:** 2010-2013 Chevrolet Camaro SS  
with a V8 Engine (RPO L99 or LS3)

**This PI was superseded to update model years. Please discard PIP4813A.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some customers may complain of a SES light, rough running, and/or lack of power. Upon inspection, DTCs P0101, P0171, P0172, P0174, and/or P0175 may be noted as well.

### Recommendation/Instructions

If this concern is encountered, inspect the hydrocarbon absorber pad that is on the inside of the air cleaner lid to ensure that it is properly secured to the lid.

If it is not secured properly, it may alter the incoming air flow, causing a skewed MAF input and any of the concerns described above.

If this concern is encountered due to a loose hydrocarbon absorber pad, replace the air cleaner lid, which should contain a new hydrocarbon absorber pad.

For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the actual cause and repair.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.