

WC55 - Replacing Oil Separator (Workshop Campaign)

Vehicle Type: **Cayenne S (92A)/Cayenne Turbo (92A)**

Model Year: **As of 2011 up to 2013**

Subject: **Replace oil separator**

Information: This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles.

Engine oil consumption can increase during deceleration on the affected vehicles if the vacuum in the crankcase is too low.

A modified oil separator is used to increase the vacuum in the crankcase and thus reduce engine oil consumption during deceleration.

Action Required: Replace oil separator.

Affected Vehicles: The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the vehicle. This campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper repair. This campaign affects 7,933 vehicles in North America.

Parts Info: **NOTE: Do not order parts. All parts required for this campaign will be automatically allocated to your dealership.**

000.043.110.15	⇒ Engine ventilation	1
Contains:		
948.107.437.20	Seal	1
948.107.438.20	Seal	1
948.107.443.01	Fastening part, M6 x 33	4

Tools: **Nr. 90 Pos. 1 - Torque wrench**
9824 - Flexible-head socket wrench a/f 8
9824/2 - Torx Micro Bit T30
Socket-wrench insert Torx E10

Work Procedure: See Attachment "A".

Claim Submission: See Attachment "B".

Attachment "A": **Work Procedure**

- 1 Remove the **oil separator** as described in the Workshop Manual ⇒ *Workshop Manual '105519 Removing and installing oil separator – section on "Removing"*.
- 2 **Install new** oil separator, Part No. **000.043.110.15** with new **seals and fastening parts** ⇒ *Workshop Manual '105519 Removing and installing oil separator - section on "Installing"*.
- 3 Enter the workshop campaign in the Warranty and Maintenance booklet.

**Information**

The specified working time was determined specifically for carrying out this campaign and may differ from the working times published in the Labor Operation List in PIWIS.

Attachment "B": **Claim Submission** - Workshop Campaign WC55

Warranty claims should be submitted via WWS/PQIS.

Open campaigns may be checked by using either the PIWIS Vehicle Information system or through PQIS Job Creation.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/PQIS. If necessary, the required part numbers will need to be manually entered into warranty system by the dealer administrator.

Working time:

Replacing oil separator

Labor time: **20 TU**

Includes: Removing and installing engine cover (cylinders 5-8)

Parts required:

000.043.110.15	Engine ventilation	1
----------------	--------------------	---

⇒ **Damage Code WC55 066 000 2**

References: ⇒ *Workshop Manual '108319 Removing and installing engine cover (design cover)'*

⇒ *Workshop Manual '105519 Removing and installing oil separator'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© Porsche Cars North America, Inc.

Dealership	Service Manager	Shop Foreman	Service Technician
Distribution			
Routing	Asst. Manager	Warranty Admin.	Service Technician

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Panamera®, Speedster®, Spyder®, 918 Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, 4S®, FOUR, UNCOMPROMISED.® and the model numbers and the distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and other elements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal use only by authorized Porsche dealers and authorized users and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.

Printed in the USA