



SP 4-286-003

SERVICE PROGRAM

May, 2013

ATTENTION:

Service Managers / Parts Managers

SUBJECT:

Transmission Oil Cooler (TOC) replacement for certain Xpeditor trucks with ISL, ISC and ISL G engines.

DESCRIPTION OF SERVICE PROGRAM:

This Service Program provides instructions to obtain replacement parts and replace the TOC on certain ACX-cab Xpeditor trucks equipped with Allison® transmission retarders. Program Expires: May 15, 2014

VEHICLES AFFECTED:

There are 85 affected vehicles with serial numbers in the range 212946 through 215865. Note that there are different Service Programs for different vehicle/engine configurations. Refer to the VIN list beginning on Page 14.

SERVICE RESPONSIBILITY:

Service Programs are performed on eligible vehicles at no charge to the owner until the expiration date listed above.

SERVICE PROGRAM INFORMATION:

Service Programs are product modifications and/or product improvements that Autocar has determined will enhance the operation of the truck. In a continuing effort to inform our customers of potential service issues and avoid unnecessary down time, Autocar has identified the following operation as

recommended preventive maintenance. This Service Program should be added to your preventive maintenance and service manuals.

While being committed to continuous product improvement, Autocar is not liable for updating existing chassis after they have been placed in service.

Questions regarding this Service Program should be directed to Autocar Technical Support at 888-218-3611.

REQUIRED PARTS:

- (1) S2860002K001 SVC KIT
 - (1) A2040182-001 Pipe, coolant
 - (1) A2040183-001 Elbow
 - (1) A2040184-001 Transition pipe
 - (1) A2860178-001 TOC
 - (2) A2860186-001 Mounting bracket
 - (8) GZ220015-006 Hose clamp
 - (1) GZ240026-001 Hose
 - (1) GZ240027-001 Hose
 - (1) GZ250017-001 #12 SAE O-ring
 - (1) GZ250017-002 #12 Facial seal O-ring
 - (4) GZ250017-003 #20 SAE O-ring
 - (2) GZ250017-004 #20 Facial seal O-ring
- (1) S2860005K001 Hardware kit
 - (4) GE286237BO01 Locknut
 - (4) GE286250BO01 Locknut
 - (4) GE410137AO12 Bolt
 - (4) GE410150AO24 Bolt

SP 4-286-003

SERVICE PROGRAM

May, 2013

TO OBTAIN PARTS:

Ensure that you have authorization from the customer to perform this work, and send an e-mail to warranty@autocartruck.com which includes the following:

- VIN(s) (or last 6 digits of VIN(s))
- 'Attention To' name
- 'Ship To' address

NOTE that the parts for this Service Program are fragile and heavy and require special packaging and shipment. The parts will be shipped on a pallet by truck and can NOT be delivered overnight. Delivery may take 3-10 days depending on volume and location.

CLAIMS FOR REIMBURSEMENT:

Submit a claim for reimbursement in accordance with Autocar's Warranty Administration Manual.

CLAIM CODING INFORMATION:

Labor Operation Code Number	Time Allowance SRT	Description
49101-5-04	4.5 HR	Trans Oil Cooler Replacement

TOOLS REQUIRED:

- 1/2" drive 9/16" socket
- 1/2" drive 5/8" socket
- 1/2" drive 7/16" socket
- 1/2" drive 3/4" socket
- 1 7/8" combination wrench
- 1 3/8" combination wrench
- 3/4" combination wrench
- 1/2" drive torque wrench capable of 150 Ft. Lb (203 Nm)
- 15 gallon (57 liter) drain pan
- 5 gallon (19 liter) drain pan

SAFETY NOTICES



WARNING

Allow the vehicle's engine and cooling system to cool to ambient temperature before performing the repair procedure. A hot engine or cooling assembly may cause burns or other personal injury.



WARNING

To prevent eye injury, always wear eye protection when performing vehicle maintenance, service or inspection.



WARNING

Before working on a vehicle, set the parking brake, place the transmission in neutral and block the wheels. Failure to do so can result in unexpected vehicle movement and can cause serious personal injury or death.



WARNING

Take proper precautions before working under the vehicle. Use ramps approved for the weight of your vehicle, or use floor jacks and stands. Never work under a vehicle supported by jacks alone. Always use jack stands to support the vehicle.

SP 4-286-003

SERVICE PROGRAM

May, 2013



CAUTION

LOCKOUT/TAGOUT PROCEDURES

Before entering the vehicle or vehicle body, read and follow OSHA regulations concerning entry and working in "CONFINED SPACE" OSHA 1910.146 and "LOCKOUT/TAGOUT" OSHA 1910.147. Follow OSHA regulations while performing any work on the vehicle. The vehicle must be disabled by the following steps before performing any work on the vehicle:

1. Place the transmission in NEUTRAL.
2. Set the parking brake.
3. Shut the engine OFF.
4. Lock cab doors, keep the key in your pocket. Block the wheels before entering the body or performing any work on the vehicle.
5. Turn the battery disconnect switch OFF, if equipped.
6. Completely drain the air from the primary/A system and secondary/B system by opening the drain valves on the air tanks themselves or by using the drain manifold if supplied. When draining the air tanks, do not look into the area where air is draining. Dirt or sludge particles may be expelled in the air stream and can cause eye injury.
7. Place magnetic "DANGER" signs on both cab doors before entering the body or performing any work on the vehicle.
8. Take proper precautions before working under the vehicle. Use ramps approved for the weight of your vehicle, or use floor jacks and stands. Never work under a vehicle supported by jacks alone. Always use jack stands to support the vehicle.



WARNING

Autocar natural gas powered vehicles require specific compliance in the service, storage and refueling procedures.

If you store or dispense Compressed Natural Gas (CNG) or Liquid Natural Gas (LNG), or if you work on CNG or LNG trucks, your location must be fully compliant with applicable codes, regulations and standards, including National Fire Protection Association (NFPA) codes, Society of Automotive Engineers (SAE) standards, American National Standards Institute (ANSI), Natural Gas Vehicle (NGV) standards, the United States Code of Federal Regulations (CFR), and your state and local fire and other applicable codes (including the California Code of Regulations and the Texas Administrative Code, as applicable).

Contact your local fire department for guidance and additional compliance information. Technicians working on Autocar trucks with CNG or LNG engines must be trained in the proper repair of CNG and LNG engines and the safe storage and dispensing of CNG and LNG.

SP 4-286-003

SERVICE PROGRAM

May, 2013

REPLACING THE TOC

Draining the Cooling System and Removing the TOC

1. After turning the key to the "OFF" position, remove the key and allow sufficient time for the vehicle to cooled down completely.
2. Raise the cab in accordance with the following safety precautions and procedures.



WARNING

Due to the danger of sustaining personal injury and/or damage to the vehicle, never attempt to raise the cab outdoors under extremely windy conditions. Strong wind conditions could force the cab beyond the normal limits of its travel. Never rely on the hydraulic pressure to hold the cab in an open position. Always use the safety pin in the cab tilt lock tube to prevent serious personal injury or death.



WARNING

Remove or secure all loose articles and close all doors before raising the cab. The area above and ahead of the cab must be clear from obstructions. Place front wheels in a straight ahead position.

Remove the pump handle from its storage on the inside of the cab near the driver or passenger seat.

Place the selector lever on the hydraulic pump in the RAISE position. Insert the pump handle into the pump and operate the handle in an up and down motion. The hydraulic cab latches will open, then the hydraulic cylinders will lift the cab until the midpoint (top) is reached.

Once the cab has reached its midpoint the cab will move forward to the fully open position. The safety pin in the cab tilt lock device must be installed when the holes line up in the sliding bar.

Remove the pump handle when not in use. It may stick out and could cause injury to passersby.

SP 4-286-003

SERVICE PROGRAM

May, 2013



WARNING

Do not remove the pressure cap from a hot engine. Wait until the coolant temperature is below 50°C [120°F] before removing the pressure cap. Heated coolant spray or steam can cause personal injury.

3. Remove the cooling system pressure cap.



WARNING

Coolant is toxic. Keep away from children and pets. If not reused, dispose of in accordance with local environmental regulations

Note: *The drained engine coolant will be reinstalled at the end of the repair procedure. Ensure that the engine coolant is drained and kept separate from the drained transmission fluid. Use two separate drain pans as noted.*

4. If equipped with an oil pan guard (skid plate), remove the 6 fasteners and set aside (fasteners and oil pan guard) for reinstallation (see Figure 1).
5. Using a 15-gallon (57-liter) drain pan, drain the cooling system by opening the drain valve on the radiator and the drain valve on the bottom of the engine oil cooler housing. Remove the TOC drain plug to completely drain the TOC (see Figure 3).

6. After the cooling system is completely drained, close the drain valves. Set the captured coolant aside for reinstallation. Refer to the engine manufacturer's instructions for complete cooling system drain procedure and information.

SP 4-286-003
SERVICE PROGRAM

May, 2013




Figure 1

SP 4-286-003 SERVICE PROGRAM

May, 2013




Figure 2

Note: The drained engine coolant will be reinstalled at the end of the repair procedure. Ensure that the engine coolant is drained and kept separate from the drained transmission fluid. Use two separate drain pans as noted.

7. Remove the coolant bypass fitting from the TOC. Remove and discard the O-rings from the fitting and set the fitting aside for reinstallation (see Figure 2).

Note: Pay particular attention to the orientation of fittings, for reinstallation. Remove the O-rings from the fittings and discard (see Figure 2).




Figure 3

8. Position a 5-gallon (19-liter) drain pan beneath the transmission fluid pipe fittings. Disconnect the 2 transmission fluid pipes from the fittings and remove the fittings from the TOC. Remove and discard the O-rings from the fittings and place the fittings aside for reinstallation. Discard the captured transmission fluid (see Figure 3).

SP 4-286-003 SERVICE PROGRAM

May, 2013




Figure 4

9. Disconnect the coolant hose (see Figure 4).




Figure 5

10. Loosen the clamps and remove the coolant hose (see Figure 5).




Figure 6

11. Remove the 4 fasteners securing the TOC to the cross member and discard the fasteners (see Figure 6).

Note: If equipped with spacers, set the spacers aside for reinstallation and discard the fasteners (see Figure 6).

12. Remove the TOC and discard.

SP 4-286-003 SERVICE PROGRAM

May, 2013




Figure 7

Installing the New TOC

13. Install the 2 mounting brackets (A2860186-001) to the cross member utilizing 4 bolts (GE410150AO24), 2 spacers (if equipped) and 4 locknuts (GE286250BO01). Tighten to 45 ft-lb (61 N-m) of torque (see Figure 7).
14. Install the new TOC (A2860178-001) onto to the mounting brackets utilizing 4 bolts (GE410137AO12) and 4 locknuts (GE286237BO01). Tighten to 45 ft-lb (61 N-m) of torque (see Figure 7).

SP 4-286-003 SERVICE PROGRAM

May, 2013




Figure 8

Note: Lubricate the O-rings and threads on the fitting with hydraulic oil prior the installation.

15. Locate the transmission pipe fittings which were set aside in step 8. Install 1 SAE O-ring (GZ250017-003) to each of the fittings leading to the TOC and 1 facial seal O-ring (GZ250017-

004) to each of the fittings leading to transmission oil pipes. Install the fittings into the new TOC; then, connect the TOC pipes (RH/LH) to the fittings. Orient the fittings as noted during removal in step 8. Tighten to 150 ft-lb (203 N-m) of torque (see Figure 8 and Figure 10).

SP 4-286-003 SERVICE PROGRAM

May, 2013

Note: On certain early production vehicles the TOC lines may be routed together on the right side of the engine, it may be necessary to invert the bracket mounted to the TOC to gain clearance for these applications, if you have questions please call 888-218-3611.




Figure 9

16. On the LH side of the TOC, install the extension hose (GZ240027-001) and 2 hose clamps (GZ220015-006) (see Figure 9).
17. On the LH side of the TOC, install the transition pipe (A2040184-001) onto the extension hose and tighten the 2 hose clamps to 60 In-lb (7 N-m) of torque (see Figure 9).

Note: Lubricate the O-rings and threads on the fitting with hydraulic oil prior the installation.

18. On the coolant bypass fitting that was set aside in step 8, install 1 SAE O-ring (GZ250017-001) to the fittings leading to the TOC and 1 facial seal O-ring (GZ250017-002) to the fittings leading to the coolant bypass hose. Install the fitting onto the transition pipe; then, connect the coolant bypass hose to the fitting. Tighten to 85 ft-lb (115 N-m) of torque (see Figure 9 and Figure 10).




Figure 10

SP 4-286-003

SERVICE PROGRAM

May, 2013




Figure 11

19. On the LH side of the TOC, install the hose (GZ240026-001) and 2 hose clamps (see Figure 11).
20. On the RH side of the TOC, using 2 hose clamps (GZ220015-006), install the elbow (A2040183-001). Tighten the hose clamps to 60 In-lb (7 N-m) of torque (see Figure 12).
21. Install the coolant pipe (A2040182-001) onto the elbow (see Figure 12).
22. Check for damaged hoses and loose or damaged hose clamps. Replace as required.
23. Check the radiator for damage and/or buildup of dirt. Clean and replace as required.

SP 4-286-003 SERVICE PROGRAM

May, 2013




Figure 12

24. Reinstall the previously captured engine coolant. Refer to the engine manufacturer's instructions for complete cooling system fill procedure and information.
25. Top off the transmission fluid using only Allison® approved synthetic oil.
26. Pressure test the cooling system to 16 psi.
27. If equipped, reinstall the oil pan guard. Tighten the 6 fasteners to 80 ft-lbs (108 N-m) of torque.
28. Lower the cab.
29. Operate the unit to verify the installation and inspect for any leaks. Once verified, the replacement of the TOC is complete.

SP 4-286-003

SERVICE PROGRAM

May, 2013

5VCACRLE2BH212946	5VCACSLE0CH214624	5VCACSLE6DH215083
5VCACRLE4BH212947	5VCACSLE2CH214625	5VCACSLE8DH215084
5VCACLLE4CH213191	5VCACSLE4CH214626	5VCACSLEXDH215085
5VCACSLE3CH213192	5VCACSLE6CH214627	5VCACSLE1DH215086
5VCA3RLE6CH213440	5VCACSLE8CH214628	5VCACSLE3DH215087
5VCA3RLE8CH213441	5VCACSLEXCH214629	5VCACRLE0DH215766
5VCA3RLEXCH213442	5VCACSLE7CH214684	5VCACRLE2DH215767
5VCA3RLE1CH213443	5VCACSLE9CH214685	5VCACRLE2DH215784
5VCA3RLE3CH213444	5VCACSLE0CH214686	5VCACRLE4DH215785
5VCA3RLE5CH213445	5VCACRLE5CH214689	5VCACRLE6DH215786
5VCA3SLE9CH213682	5VCACRLE1CH214690	5VCACD8F6DH215811
5VCA3SLE0CH213683	5VCACRLE3CH214691	5VCACR8F9DH215864
5VCA3SLE2CH213684	5VCACRLE5CH214692	5VCACR8F0DH215865
5VCACSLE9CH214198	5VCACRLE7CH214693	
5VCACSLE0CH214199	5VCACRLE9CH214694	
5VCACRLEXCH214218	5VCACRLE5DH214919	
5VCACRLE1CH214219	5VCACRLE1DH214920	
5VCACRLE8CH214220	5VCACRLE3DH214921	
5VCACRLEXCH214221	5VCACRLE5DH214922	
5VCACRLE1CH214222	5VCACRLE7DH214923	
5VCACRLE3CH214304	5VCACRLE9DH214924	
5VCACRLE5CH214305	5VCACRLE0DH214925	
5VCACRLE7CH214306	5VCACRLE2DH214926	
5VCACRLE9CH214307	5VCACRLE4DH214927	
5VCACRLE0CH214308	5VCACRLE6DH214928	
5VCACRLE2CH214309	5VCACRLE8DH214929	
5VCACRLE9CH214310	5VCACRLE4DH214930	
5VCACRLE0CH214311	5VCACRLE6DH214931	
5VCACRLE2CH214312	5VCACRLE8DH214932	
5VCACRLE4CH214313	5VCACSLE7DH215030	
5VCACRLE6CH214314	5VCACSLE9DH215031	
5VCACRLE8CH214315	5VCACSLE0DH215032	
5VCACRLEXCH214316	5VCACSLE2DH215033	
5VCACLLE1CH214413	5VCACLLE9DH215035	
5VCACSLE7CH214622	5VCACLLE0DH215036	
5VCACSLE9CH214623	5VCACLLE2DH215037	