

© 2013 Mazda Motor of America, Inc.

Subject: REAR MOUNT CAMERA DOES NOT OPERATE	Bulletin No: 09-016/13
	Last Issued: 05/07/2013


APPLICABLE MODEL(S)/VINS

2013 CX-5 with VINs lower than JM3KE*****155008 (produced before October 7, 2012)

DESCRIPTION

Some vehicles may exhibit an inoperative rear mount camera. This concern may be caused by water entering inside the camera during a high-pressure car wash.

The shape of the camera has been changed to eliminate this concern.




Customers having this concern should have their vehicle repaired using the following repair procedure.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


REPAIR PROCEDURE

1. Verify the customer concern.
2. Inspect the rear mount camera according to the instructions on MS3 online or the Workshop Manual (section 09-20 REAR MOUNT CAMERA INSPECTION).
3. If the rear mount camera is found to be faulty, replace it with a modified one according to the instructions on MS3 online or the Workshop Manual (section 09-20 REAR MOUNT CAMERA REMOVAL/INSTALLATION).
4. Locate the opener switch connector (A).



5. Attach a water-proof sheet over the opener switch connector as shown below.

NOTE: Be sure to attach a water-proof sheet, even if the vehicle did not originally have one installed.



6. Verify the repair.

Bulletin No: 09-016/13
© 2013 Mazda Motor of America, Inc.

Last Issued: 05/07/2013

PART(S) INFORMATION

Part Number	Description	Qty.
KD33-67-RC0B	Rear Mount Camera	1
BC1B-58-862	Water-proof sheet	1

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	61
Damage Code	9K
Part Number Main Cause	KD33-67-RC0B
Quantity	1
Operation Number / Labor Hours:	XXJ6GXRX / 0.5 Hrs.