

**DOME LAMP INOPERATIVE WHEN UNLOCKING—  
INTEGRATED KEYLESS TRANSMITTER (IKT) FOB—  
BUILT ON 11/21/2012 AND THROUGH 3/30/2013**

**TSB 13-6-6**

**FORD:**  
2013 Focus

**ISSUE**

Some 2013 Focus vehicles equipped with IKT keys and built on 11/21/2012 and through 3/30/2013 may exhibit the dome light not illuminating when unlocking the vehicle with the IKT fob unlock button after the vehicle has been left engine off and undisturbed for 30 minutes or more.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

1. Verify the dome light does not illuminate when unlocking the vehicle with the IKT fob unlock button after the vehicle has been left with engine off and undisturbed for 30 minutes or more.
2. Press the lock button on the IKT fob and then press the unlock button on the IKT fob again. Did the dome light turn on?
  - a. Yes - proceed to Step 3.
  - b. No - this article does not apply. Refer to Workshop Manual, Section 417-02 for normal diagnostics.

3. Reprogram the body control module (BCM) to the latest calibration using IDS release 84.01 and higher. Calibration files may also be obtained at [www.motorcraft.com](http://www.motorcraft.com).

**WARRANTY STATUS:** Eligible Under Provisions Of New Vehicle Limited Warranty Coverage  
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB.  
Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
130606A	2013 Focus: Identify Customer Concern And Reprogram The BCM (Do Not Use With Any Other Labor Operations)	0.3 Hr.
<b>DEALER CODING</b>		
<b>BASIC PART NO.</b>		<b>CONDITION CODE</b>
14A068		42

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.