

Technical Service Bulletin

01 MIL on (DTC P01C900 and P008800 - fuel rail pressure too high); noises from engine compartment

01 13 36 2035235/1 October 9, 2013.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|---------------|-------------|-----------|----------------------------|
| S6, S7, A8/S8 | 2013 - 2014 | All | 4.0 TFSI engine |

Condition

- The customer reports that the engine warning light illuminates sporadically (Figure 1).
- The engine may have reduced performance without significant loss of power or stalling.
- Noise is heard coming from the engine compartment, specifically from the High Pressure Fuel Pumps 2.
- The following DTCs are stored in the engine control module (ECM), J623 (address word 01):
 - DTC P008800 (fuel, rail/system pressure too high)
 - DTC P01C900 (fuel, rail/system pressure bank 2 too high)

Technical Background

The fuel metering valve of the high-pressure fuel pump is controlled by a specific on/off ratio. If there is a low system voltage, the on/off ratio may not be enough to keep the fuel metering valve constant in all areas. In such a situation, the fuel metering valve is deactivated and the high-pressure fuel pump switches to full supply mode. Because the increased rail pressure does not match the respective driving situation, the DTC appears.

Production Solution

ECM software update.



Figure 1. Engine warning light.



All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Service

SVM Update Instructions

- 1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 2. Update the ECM software using the SVM action code as listed in the table below if necessary.

| Model | Engine | Old Software Part Number | Old Software Version | New Software Part Number | New Software Version (or higher) | SVM Action Code |
|---------------|-----------|-----------------------------|----------------------------|-----------------------------|--|--------------------|
| S6/S7 (MY 13) | 4.0T CEUC | 4G0906014B | 0006 | 4G0906014E | 0002 | 01A148 |
| A8 (MY13) | 4.0T CEUA | 4H0906014B | 0003 | 4H0906014L | 0003 | 01A148 |
| S8 (MY13) | 4.0T CGTA | 4H0907557B | 0004 | 4H0907557E | 0002 | 01A148 |
| S6/S7 (MY14) | 4.0T CEUC | 4G0906014E | 0001 | 4G0906014E | 0002 | 01A148 |
| A8 (MY14) | 4.0T CEUA | 4H0906014L | 0002 | 4H0906014L | 0003 | 01A148 |
| S8 (MY14) | 4.0T CGTA | 4H0907557E | 0001 | 4H0907557E | 0002 | 01A148 |

Warranty

| Service Number: | 2470 | | | | | |
|-------------------|--|------------------------|---------|--|--|--|
| Damage Code: | 0039 | | | | | |
| Labor Operations: | Update ECM software by SVM | 2470 2599 | 40 TU | | | |
| Diagnostic Time: | GFF | 0150 0000 | 10 TU | | | |
| | Road test prior to service procedure | No allowance | 0 TU | | | |
| | Road test after service procedure | No allowance | 0 TU | | | |
| | Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online | e for DADP allowance d | etails) | | | |
| Claim Comment: | As per TSB # 2035235/1 | | | | | |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

© 2013 Audi of America, Inc.

Page 2 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Required Parts and Tools

Approved battery charger

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

• TSB 2011732: 00 Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2035235) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.

© 2013 Audi of America, Inc.

Page 3 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.