

© 2013 Mazda Motor of America, Inc.

Subject: UNABLE TO LOWER REAR SEATBACK WITH REMOTE HANDLE / SEATS HARD TO LOCK	Bulletin No: 09-013/13
	Last Issued: 04/29/2013

BULLETIN NOTE


- This bulletin supersedes the previous bulletin 09-042/12, issued on 11/07/12. The APPLICABLE MODEL(S)/VINS and REPAIR PROCEDURE have been revised.
- Changes are noted below in Red beside the change bar.

APPLICABLE MODEL(S)/VINS

2013-2014 CX-5 vehicles equipped with a 4:2:4 split type rear seat with VINs lower than JM3KE*****318331 (produced before Feb. 1, 2013)

DESCRIPTION

Some vehicles equipped with a 4:2:4 split type rear seat may be unable to lower the rear seatback (A) when pulling the left (B) and/or right (C) remote handles. Also, the seatbacks may not fully latch (lock) when placed in the upright position.



This concern may be caused by an incorrect seatback remote cable adjustment position. The current adjustment position may not provide enough tension for the cable to unlock the seatback latches.


The position of the seatback remote cable adjustment has been changed to the center position at mass-production.

Customers with this concern should have their vehicle repaired according to the following repair information.


REPAIR PROCEDURE

NOTE: This repair only applies to vehicles equipped with a 4:2:4 split type rear seat.

1. Verify the customer concern.
2. Lower the rear seatbacks using the seatback knobs.




3. From the rear cargo area, lift and fold the trunk board forward and out of the way.




4. Locate the remote cable adjuster (A) for the left seat (B), center seat (C) and right seat (D).


NOTE: Each seat has a separate cable and cable adjuster.



Left Seat: (white label = left seat back (B)) and **Center Seat:** (red label = center seat back (C))




Right Seat: (white label = right seat back (D))



- Using a small flathead screwdriver, pop open the affected remote cable adjuster housing and check the current cable adjustment setting position (1, 2 or 3) as shown below.


NOTE: Cable adjustment setting position "3" is the factory setting for vehicle produced before Feb. 1, 2013.



- Pull the cable out of the housing and change the setting to position "2", then snap the remote cable adjuster housing closed.
- Using the appropriate remote handle lever, check the seat back for proper releasing and locking operation.

NOTE:

- If changing the setting to position "2" does not fix the concern, change the setting to position "1", but make sure the seat back can be fully and properly locked after the adjustment is made.
- The red seat knob indicator must be visible when the seat back is in the unlocked position (seat knob down) and must not be visible when the seat is fully locked (seat knob up).



- Verify repair.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	41
Damage Code	9H
Part Number Main Cause	C001-56-723A (remote handle case)
Quantity	0
Operation Number / Labor Hours:	XXH34XRX / 0.2 Hrs. (adjust one, two or three seatbacks)

NOTE: This repair only applies to vehicles equipped with a 4:2:4 split type rear seat.