	GROUP	MODEL		
HYUNDAI NEW THINKING. NEW POSSIBILITIES.	FUEL SYSTEM	ACCENT (MC)		
Technical Convice Pullatin	DATE	NUMBER		
rechnical Service Bulletin	NOVEMBER 2013	13-FL-012		
SUBJECT ECM UPDATE - MIL ON DTC P0300-P0304, P0128, P0328, P0461				



NOTE: This bulletin supersedes 10-FL-004 and 10-FL-011.

Description:

This bulletin provides information for an ECM diagnostic code logic update on some Accent 1.6L vehicles that may experience the following DTC:

- P0300: Random/Multiple Cylinder Misfire Detected.
- P0301: Cylinder 1 Misfire Detected.
- P0302: Cylinder 2 Misfire Detected.
- P0303: Cylinder 3 Misfire Detected.
- P0304: Cylinder 4 Misfire Detected.
- P0128: Coolant Thermostat (Coolant Temperature Below Thermostat Regulating Temperature).
- P0328: Knock Sensor 1 Circuit High Input.
- P0461: Fuel Level Sensor A Circuit Range/Performance.

NOTE: This ECU Update is intended for the above DTCs when a performance issue was not described by Customer and the Technician has confirmed there are no performance issues. In cases where a performance issue is confirmed:

- DTC P0300-P0304 that incurred rough running/misfire must be diagnosed per existing service manual procedures.
- This ECU Update should be performed in addition to repairs that are performed.
- Parts replaced to address above DTCs are subject to WTC part recall to verify part condition and may be subject to claim chargeback if not verified.

Applicable Vehicles:

• 07~11 MY ACCENT(MC) 1.6L.

GDS Information:

EVENT #	DESCRIPTION
316 (or later compatible event)*	"316.MC 1.6 P030X, P0328, P0461 DTC LOGIC IMPROVEMENT"

(* the latest event that shows up in the Engine Auto Mode event list for the particular vehicle/engine)

Warranty Information:

Model	Op Code	Operation	Op Time	Causal P/N	Nature	Cause
ACCENT (MC)	39110F9L	ECM UPGRADE	0.3	(See NOTE)	N69	C40

NOTE: Use the applicable ECM P/N listed in the ROM ID Information Table from the following page.

SUBJECT : ECM UPDATE - MIL ON DTC P0300-P0304,P0128,P0328,P0461

ROM ID INFORMATION TABLE:

			ROM ID		
MY ECM P/N		T/M	Previous	New	
07MY	39111-26BE0	MT	GMC-7N6CES0-5000 GMC-7N6CES1-5000 GMC-7N6CES2-5000 GMC-7N6CES3-5000 GMC-7N6CES4-5000 GMC-7N6CES5-5000 GMC-7N6CES6-5000 GMC-7N6CES7-5000 GMC-7N6CES9-5000 GMC-7N6CESA-5000 GMC-7N6CEST-5000	GMC-7N6CEF0-5000	
	39111-26BE5	AT	GMC-7N6CPS0-A000 GMC-7N6CPS1-A000 GMC-7N6CPS2-A000 GMC-7N6CPS3-A000 GMC-7N6CPS4-A000 GMC-7N6CPS5-A000 GMC-7N6CPS6-A000 GMC-7N6CPS7-A000 GMC-7N6CPS8-A000 GMC-7N6CPS9-A000 GMC-7N6CPSA-A000 GMC-7N6CPSA-A000	GMC-7N6CPF0-A000	
08MY	39111-26BE1	MT	GMC-8N6CES0-5000 GMC-8N6CES1-5000 GMC-8N6CES2-5000 GMC-8N6CES3-5000 GMC-8N6CES4-5000 GMC-8N6CES5-5000 GMC-8N6CES6-5000 GMC-8N6CEST-5000 GMC-8N6CEF0-5000 GMC-8N6CEF1-5000	GMC-8N6CEF2-5000	
	39111-26BE6	AT	GMC-8N6CPS0-A000 GMC-8N6CPS1-A000 GMC-8N6CPS2-A000 GMC-8N6CPS3-A000 GMC-8N6CPS4-A000 GMC-8N6CPS5-A000 GMC-8N6CPS6-A000 GMC-8N6CPST-A000 GMC-8N6CPF0-A000 GMC-8N6CPF1-A000	GMC-8N6CPF2-A000	

TSB #: 13-FL-012

Page 2 of 6

ECM UPDATE - MIL ON DTC P0300-P0304,P0128,P0328,P0461

09MY	39131-26BE1	MT	GMC-9N6CES1-5000 GMC-9N6CES2-5000 GMC-9N6CES3-5000 GMC-9N6CES4-5000 GMC-9N6CES5-5000 GMC-9N6CES6-5000 GMC-9N6CES7-5000 GMC-9N6CEST-5000 GMC-9N6CEF0-5000 GMC-9N6CEF1-5000	GMC-9N6CEF2-5000
	39131-26BE6	AT	GMC-9N6CPS1-A000 GMC-9N6CPS2-A000 GMC-9N6CPS3-A000 GMC-9N6CPS4-A000 GMC-9N6CPS5-A000 GMC-9N6CPS6-A000 GMC-9N6CPS7-A000 GMC-9N6CPST-A000 GMC-9N6CPF0-A000 GMC-9N6CPF1-A000	GMC-9N6CPF2-A000
10MY	39132-26BL0	MT	GMC-AC6CES0-5000 GMC-AC6CES1-5000 GMC-AC6CES2-5000 GMC-AC6CES3-5000 GMC-AC6CEF0-5000 GMC-AC6CEF1-5000	GMC-AC6CEF2-5000
	39132-26AL0	MT	GMC-AN6CES0-5000 GMC-AN6CES1-5000 GMC-AN6CES2-5000 GMC-AN6CEF0-5000 GMC-AN6CEF1-5000	GMC-AN6CEF2-5000
	39132-26AL5	AT	GMC-AN6CPS0-A000 GMC-AN6CPS1-A000 GMC-AN6CPS2-A000 GMC-AN6CPF0-A000 GMC-AN6CPF1-A000	GMC-AN6CPF2-A000
	39133-26BL0	MT	GMC-BC6CES0-5000 GMC-BC6CEF0-5000 GMC-BC6CEF1-5000	GMC-BC6CEF2-5000
	39133-26AL0	MT	GMC-BN6CES0-5000 GMC-BN6CEF0-5000 GMC-BN6CEF1-5000	GMC-BN6CEF2-5000
11MY	39133-26AL5	AT	GMC-BN6CPS1-A000 GMC-BN6CPF0-A000	GMC-BN6CPF1-A000
	39134-26BL0	MT	GMC-CC6CES1-5000 GMC-CC6CEF0-5000	GMC-CC6CEF1-5000
	39134-26AL0	MT	GMC-CN6CES1-5000 GMC-CN6CEF0-5000	GMC-CN6CEF1-5000

GENERAL PRECAUTIONS:

- Connect the USB cable between the GDS and the VCI.
- Connect the 16-pin DLC connector from the VCI into the DLC located under the driver's side dash.



* NOTE

Make sure the battery icon at the bottom right of the GDS laptop shows at least 50%; if not, charge the GDS or attach a battery charger.

- Turn off all lights (Do not leave the headlight switch in auto mode) and all accessories (including heater/air conditioner/fan, audio, heated seats, rear defroster, etc) to ensure the battery will not be discharged during the update.
- Perform the update with the ignition key in the ON position.
- Do not disconnect any cables connected to the vehicle or the GDS during the update.
- Do not start the engine or turn the ignition switch OFF during the update.

* NOTE

Confirm your GDS has the most recent version. If not, connect the GDS to an Internet port, open the GDS home page and select "Update". Refer to instructions on hmaservice.com if necessary.

If you encounter GDS related problems, call the GIT Helpline at 888-437-0308.

ECM UPDATE - MIL ON DTC P0300-P0304,P0128,P0328,P0461

SERVICE PROCEDURE:

GDS AUTO MODE ECM UPDATE PROCEDURE

- 1. From the GDS home page, select ECU Upgrade. If necessary, select the VIN.
- 2. Select **Engine** as the system and then select **OK**.
- 3. Select Auto Mode and then select Next.
- 4. From the **System** tab, select **Engine** and then select **OK**. The GDS will read the ROM ID and confirm the update applies.



5. Select update event as listed on the GDS Event list of page-1. Select Upgrade.



- 6. If the screen indicates "Voltage is OK" (voltage > 12volts), select OK. If not, select CANCEL and charge the vehicle battery by running the engine for 10 minutes.
- 7. Updating will occur until 100% is reached on the bar graph. At the prompt, turn the ignition key OFF for 10 seconds, then turn it ON and select **OK**.
- 8. The GDS will confirm that ECM reprogramming is successfully finished. Select OK.
- 9. If the ECM update was not successful, go to GDS MANUAL MODE <u>ECM</u> UPDATE PROCEDURE.
- 10. Check for DTC in All Systems and Erase All DTC that stored due to loss of CAN communication during the ECM Update.
- 11. Turn **OFF ignition for 10 seconds** then turn **ON** before going to engine start.
- 12. Start the engine to confirm proper operation.

SUBJECT : ECM UPDATE - MIL ON DTC P0300-P0304,P0128,P0328,P0461

GDS MANUAL MODE ECM UPDATE PROCEDURE

	* NOTE			
 GDS Manual Mode is intended for recovery of an ECM Update should it begin but then later fail in process in the Auto Mode. The ECM connectors must be disconnected for 15 minutes to reset its contents then perform this Manual Mode Update. Do not force Manual Mode if you get an error in Auto Mode that the vehicle current ROM ID did not apply. It is critical to identify the correct ECM Part Number in the PASSWORD ta 				
	ECM and	d read the part number from the label to confirm.		

- 1. From the GDS home page, select **ECU Upgrade**. If necessary, select the VIN.
- 2. Select Engine as the system and then select OK.
- 3. Select Manual Mode and then select Next.
- 4. From the System tab, select Engine and then select OK.
- 5. Select update event as per the GDS Event List of page-1, then select Upgrade.
- 6. Be certain to enter the exact appropriate password from the table below and select **OK**. See the important NOTE above.
- 7. The remaining steps are same as Steps 6~12 of the Auto Procedure.

MENU	PASSWORD
07MY MC 1.6 MT NON IMMO : 39111-26BE0	1260
07MY MC 1.6 AT NON IMMO : 39111-26BE5	1265
08MY MC 1.6 MT NON IMMO : 39111-26BE1	1261
08MY MC 1.6 AT NON IMMO : 39111-26BE6	1266
09MY MC 1.6 MT NON IMMO : 39131-26BE1	1262
09MY MC 1.6 AT NON IMMO : 39131-26BE6	1267
10MY MC 1.6 MT NON IMMO : 39132-26BL0	2260
10MY MC 1.6 MT NON IMMO : 39132-26AL0	2261
10MY MC 1.6 AT NON IMMO : 39132-26AL5	2265
10MY MC 1.6 MT NON IMMO : 39133-26BL0	3260
10MY MC 1.6 MT NON IMMO : 39133-26AL0	3261
11MY MC 1.6 AT NON IMMO : 39133-26AL5	3265
11MY MC 1.6 MT NON IMMO : 39134-26BL0	4260
11MY MC 1.6 MT NON IMMO : 39134-26AL0	4261