T-SB-0061-13



Abnormal Power Door Lock Operation (Cycle)

 Service
 Category
 Vehicle Interior
 Toyota Supports

 Section
 Door Lock
 Market
 USA

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2009 – 2011	Corolla, Matrix	WMI(s): 2T1	

Introduction

Some vehicles may exhibit a condition where the door locks cycle without any operator input of a door lock switch or keyless remote assembly. In limited cases this condition may be caused by grease contamination in the door lock switch. The following procedure is available to inspect and diagnose this condition. Replacement instructions for the door wire harness and door lock actuator are also provided in this bulletin.

Production Change Information

This bulletin applies to:

- All 2009 2010 model year Corolla and Matrix vehicles.
- All 2011 model year Corolla, Matrix produced **BEFORE** the Production Change Effective VINs* shown below.

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Corolla	2T1BU4EE#BC653555
Matrix	2T1KU4EE#BC653562

* For detailed information on VINs, please reference the 2009 / 2010 / 2011 VIN Decoder Chart found on the Technical Information System (TIS), under *Reference Information: Technician Group.*

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Plastic Pry Tool Set*	00002-06000-01	1

* Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

TOYOTA T-SB-0061-13

0.7

Page 2 of 20

1

Abnormal Power Door Lock Operation (Cycle)

Parts Information

PART NUMBER	PART NAME	QTY
82151-02J90	RH Front Door Wire	1
82152-02J90	LH Front Door Wire	
69030-06200	FR Door Motor RH w/Lock Assy	
69040-06180	FR Door Motor LH w/Lock Assy	1
82152-02G90	Wire, Front Door, LH	1
82152-02J00	Wire, Front Door, LH	1
82152-02J20	Wire, Front Door, LH	1
82152-02J30	Wire, Front Door, LH	1
82151-02J10	Wire, Front Door, RH	1
82151-02J20	Wire, Front Door, RH	1
82151-02J40	Wire, Front Door, RH	1
82151-02J50	Wire, Front Door, RH	1
82152-02J50	Wire, Front Door, LH	1
82152-02J60	Wire, Front Door, LH	1
821 <mark>52-02</mark> J70	Wire, Front Door, LH	1
82152-02K00	Wire, Front Door, LH	1
82152-02K10	Wire, Front Door, LH	1
82152-02K20	Wire, Front Door, LH	1
82152-02K40	Wire, Front Door, LH	1
82152-02K60	Wire, Front Door, LH	1
82152-02N00	Wire, Front Door, LH	1
82151-02J70	Wire, Front Door, RH	1
82151-02J80	Wire, Front Door, RH	1
82151-02K10	Wire, Front Door, RH	1
82151-02K20	Wire, Front Door, RH	1
82151-02K30	Wire, Front Door, RH	1
82151-02K40	Wire, Front Door, RH	1
82151-02L20	Wire, Front Door, RH	1
82151-02L50	Wire, Front Door, RH	1
82151-02N90	Wire, Front Door, RH	1

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EL1221	Inspect Wire Harness (Both Sides)	0.8	69030-06200*		
Combo A	Wire Harness and Door Lock Replacement (One Side)	1.2	69040-06180* 82151-02J90 82152-02J90		
Combo B	Opposite Side	1.2	82152-02G90 82152-02J00 82152-02J20 82152-02J30 82151-02J10 82151-02J20 82151-02J50 82152-02J50 82152-02J50 82152-02J70 82152-02K00 82152-02K10 82152-02K40 82152-02K40 82152-02K40 82151-02J70 82151-02J80 82151-02K10 82151-02K30 82151-02K30 82151-02K40 82151-02L20 82151-02L50 82151-02L90	87	17

* Represents door lock assemblies.

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Overview

The procedures listed will be used to inspect the specified connectors for grease contamination and will outline the replacement of the wire harnesses and door lock actuators if contamination is present.

Inspection Procedure

NOTE

- Inspect both the LH and RH side.
- The procedures listed are for inspecting the LH side.
- Use the same procedures to inspect the RH side.
- 1. Verify the door locks cycle without any operator input from a door lock switch or keyless remote assembly.
 - If YES proceed to step 2.
 - If NO STOP! This bulletin does NOT apply.

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual for further diagnosis.


2009 / 2010 / 2011 Corolla:

Vehicle Interior – Door Lock – "Door Lock: Power Door Lock Control System: How To Proceed with Troubleshooting"

• 2009 / 2010 / 2011 Matrix:

Vehicle Interior – Door Lock – "Door Lock: Power Door Lock Control System: How To Proceed with Troubleshooting"


2. Using a plastic pry tool, disengage the 3 claws and remove the driver door inside handle bezel.



© 2013 Toyota Motor Sales, USA


Inspection Procedure (Continued)

- Remove the front armrest upper base panel (w/o power window).
 - A. Using a plastic pry tool, disengage the 2 clips and 6 claws, and remove the front armrest upper base panel.
 - B. Disconnect the door lock switch connector.



1	Clip
2	Claw

- Remove the front armrest upper base panel (w/ power window).
 - A. Using a plastic pry tool, disengage the 2 clips and 6 claws.
 - B. Disconnect the master switch connector and remove the front armrest upper base panel.




1	Clip
2	Claw

Inspection Procedure (Continued)


- 5. Remove the front door trim board sub-assembly.
 - A. Using a screwdriver with its tip wrapped with protective tape, disengage the claw and disconnect the door armrest cap.

Figure 4.



1 Protective Tape

Figure 5.



B. Remove the 2 screws.

Inspection Procedure (Continued)

- C. Using a clip remover, disengage the 10 clips around the door panel.
- D. Disengage the 5 claws and separate the front door trim board sub-assembly from the front door inner glass weatherstrip.






Figure 7.

E. Disengage the 2 claws and disconnect the front door inside handle sub-assembly.




Inspection Procedure (Continued)

6. Disengage the 8 claws and remove the front door Figure 8. scuff plate LH.



Door Wire Harness Inspection

- 1. Remove the front door lower frame bracket garnish (w/ front No. 2 speaker).
 - A. Disengage the clip and clamp.
 - B. Disconnect the speaker connector and remove the front door lower frame bracket garnish.




Inspection Procedure

Door Wire Harness Inspection (Continued)

- 2. Remove the front door service hole cover.
 - A. Disconnect the door lock connector.



Figure 11.



B. Remove the front door service hole cover (plastic sheet).


NOTICE

Remove plastic cover carefully to prevent tearing of plastic sheet.

HINT

Remove any remaining butyl tape from the door.


C. Unclip door wire harness mounting clips using a clip remover or blade screwdriver.



Inspection Procedure

Door Wire Harness Inspection (Continued)

3. Inspect the following connectors for contamination. Figure 12. Corolla ONLY



Α	15 – Front Door Lock Assembly LH


B I8 – Front Door Lock Control Switch Assembly LH

C H6 – Front Door Lock Assembly RH D H9 – Front Door Lock Control Switch Assembly RH

Inspection Procedure

Door Wire Harness Inspection (Continued)

Figure 13. Matrix ONLY



A. If grease contamination is NOT found, STOP! This bulletin does NOT apply.

Refer to TIS, applicable model and model year Repair Manual for further diagnosis.

• <u>2009</u> / <u>2010</u> / <u>2011</u> Corolla:

Vehicle Interior – Door Lock – "Door Lock: Power Door Lock Control System: How To Proceed with Troubleshooting"

• <u>2009 / 2010 / 2011</u> Matrix:

Vehicle Interior – Door Lock – "Door Lock: Power Door Lock Control System: How To Proceed with Troubleshooting"

NOTE

Assembly LH

Reassemble in reverse order of inspection.

Inspection Procedure

Door Wire Harness Inspection (Continued)


B. If any of the above connectors are contaminated with grease, continue to Repair Procedure to replace the wire harnesses and door lock actuators on the affected side.

Repair Procedure

Door Wire Harness Removal

HINT

- The procedures listed are for repairing the LH side if grease contamination is found.
- Use the same procedures to repair the RH side if grease contamination is found in the specified connectors.
- 1. Remove the cowl side trim board LH.
 - A. Disengage the clip and guide, and remove the cowl side trim board LH. Figure 14.




B. Disconnect harness connectors in kick panel.

Repair Procedure

Door Wire Harness Removal (Continued)

2. Loosen the rubber boot in door jamb (at bottom of Figure 15. A pillar and leading edge of door).




Repair Procedure

Door Wire Harness Removal (Continued)

3. Pull door harness into door from kick panel and door jamb to remove from the door.

Figure 16.



Door Lock Assembly Removal

1. Remove the bolt and the front door rear lower frame sub-assembly.

Figure 17.





Figure 18.


Abnormal Power Door Lock Operation (Cycle)

Repair Procedure

Door Lock Assembly Removal (Continued)

- 2. Remove the front door lock assembly.
 - A. Using a T30 Torx bit, remove the 3 screws.
 - B. Slide the front door lock assembly downward, and remove the front door lock assembly and cables as a unit.
 - C. Remove the door lock wiring harness seal from the front door lock assembly.







Repair Procedure

Door Lock Assembly Removal (Continued)

- 4. Remove the front door inside locking cable assembly.
 - A. Using a screwdriver, disengage the 3 claws.


Figure 20.





B. Remove the front door inside locking cable assembly.






Repair Procedure (Continued)

Door Lock Assembly Installation

- 1. Install the front door inside locking cable assembly.
 - A. Install the front door inside locking cable assembly.





B. Engage the 3 claws.






Figure 24.

- C. Install the front door lock remote control cable assembly.

Repair Procedure

Door Lock Assembly Installation (Continued)


2. Install the front door lock assembly.

NOTICE

Reusing the door lock wiring harness seal or using a damaged door lock wiring harness seal may cause water intrusion. This may result in a malfunction of the front door lock assembly.

NOTE


- When reusing the removed front door lock assembly, replace the door lock wiring harness seal on the connector with a new one.
- Do NOT allow grease or dust to adhere to the door lock wiring harness seal surface of the connector.
- A. Apply MP grease to the sliding parts of the front door lock assembly.
- B. Install a NEW door lock wiring harness seal to the front door lock assembly.
- C. Insert the front door lock open rod to the front door lock assembly.
- D. Make sure that the front door lock open rod is securely connected to the front door lock assembly.
- E. Using a T30 Torx bit, install the 3 screws. Torque: 5.0 N*m (51 kgf*cm, 44 in*lbf)



Repair Procedure

Door Lock Assembly Installation (Continued)

- 3. Install the front door rear lower frame sub-assembly.
 - Torque: 6.2 N*m (63 kgf*cm, 55 in*lbf)



Door Wire Harness Installation

 Install the NEW door wire harness by pulling the leading edge connectors of the door harness from inside door, through the hole in front of the door, and into the hole to access the kick panel.

NOTICE

Be careful NOT to chafe wires on metal edges when pulling harness through the holes.

Figure 27.




Repair Procedure

Door Wire Harness Installation (Continued)

2. Secure the rubber boot on both sides of door jamb.

NOTE

Be sure both rubber boots are completely seated in the door jamb and base of the A pillar.



Vehicle Assembly Procedure

- 1. Complete assembly in reverse order of inspection procedure.
- 2. Confirm repair by ensuring that the locks do NOT cycle without any operator input from a door lock switch or keyless remote assembly.

© 2013 Toyota Motor Sales, USA.