



NUMBER: 08-043-13 REV. A

GROUP: Electrical

DATE: July 19, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-043-13 DATED JUNE 11, 2013 WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ONE CAUTION NOTE.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-039. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 13.04 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: SRT Auto Transmission, Adding Launch Control Feature

OVERVIEW:

This bulletin involves updating the Anti-lock Brake System (ABS) module, Cluster and Totally Integrated Power Module (TIPM), if required.

MODELS:

2013	(LD)	Charger (SRT only)
2013	(LX)	300 (SRT only)
2013	(LC)	Challenger (SRT only)

NOTE: This bulletin applies to vehicles Built on or before November 28, 2012 (MDH 1128XX) equipped with 5-Speed auto W5A580 Transmission (sales code DGJ)

SYMPTOM/CONDITION:

The customer may note that the launch control feature is missing.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTC's are set. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the ABS module and the Cluster.
2. Flash reprogram the modules. Help using the wiTECH Diagnostic Application for flashing the ABS/Cluster is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
3. Is this vehicle a (LC) Challenger?
 - a. Yes >>> The TPIM also needs to be reprogrammed, proceed to [Step #4](#).
 - b. No >>> Proceed to [Step #5](#).
4. Flash reprogram the TIPM. Help using the wiTECH Diagnostic Application for flashing the Amplifier is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
5. Clear any DTC's that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.
6. Using the wiTECH™ application run "ABS initialization". From the ABS View screen select Misc Functions tab to run the initialization.

CAUTION: **If the vehicle has under 500 Miles, the Launch control feature will not operate and will display "Not Available". The vehicle will need 500 miles of proper break-in time before Launch control will be available.**

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-10-92	Module, ABS and cluster - Reprogram (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.4 Hrs.
18-19-10-93	Module, ABS, cluster and TIPM - Reprogram (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.4 Hrs.

FAILURE CODE:

FM	Flash Module
----	--------------