



Service Bulletin

File in Section: -

Bulletin No.: PIT5199

Date: February, 2013

PRELIMINARY INFORMATION

Subject: Whistle Wind Noise From Drivers Side Mirror Area

Models: 2012 - 2013 Chevrolet Equinox
2012 - 2013 GMC Terrain

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customer may comment on a high pitched whistle or wind noise from the driver's side mirror area between speeds 25 to 52 mph. This may be caused by a gap between the belt molding and the bottom of mirror mounting patch. This may be caused by a void in the sealing area in the corner of the belt molding and the door glass frame at the front toward the A pillar. See picture below.



3277930

Recommendation/Instructions

Suggest using a rubber mallet and lightly tapping on the belt molding moving it toward the A pillar area. This will close the gap slightly. Use a suitable piece of rubber and glue it to the rubber seal portion of the belt molding. This will fill the remaining void in the seal. Use a piece of tape to keep it in place until the glue dries.



3277931



3277932

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
B6818 *	Wind Whistle Door Mirror Repair	0.3hr

* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide. Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.