



# Service Bulletin

File in Section: -

Bulletin No.: PIP5080B

Date: February, 2013

## PRELIMINARY INFORMATION

**Subject:** Intermittent Service 4WD Message With Any Of The Following DTCs C0306 C0321 C0398 C0396 C0569

**Models:** 2012-2013 Chevrolet Silverado, Tahoe, Suburban, Avalanche  
2012-2013 GMC Sierra, Yukon  
Equipped with 4wd RPO NP0 NQF or NQH

**This PI was superseded to update DTCs. Please discard PIP5080A.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some customers may comment on a service 4 wheel drive message displayed in the driver's information center. Diagnostic trouble codes may include any one of, or any combination of the following C0306 C0321 C0398 C0396 C0569.


### Recommendation/Instructions

Review the wiring schematics for the related diagnostic trouble code. Recent warranty reviews of transfer case control module and transfer case actuator motors have returned a high number of no trouble found parts and subsequent warranty claims for wiring repairs related to X109 and X3.


Before replacing transfer case control module or actuator motors review terminals at X109 and X3 for proper tension, crimp, fully seated and overall condition.

Along with X109, terminals in X3 of the transfer case control module has been a source for diagnostic trouble codes C0306 and C0569 as this connector houses the motor AB circuits (1552/1553).

For diagnostic trouble code C0321 circuit 1342 at X109 has been an area to inspect thoroughly.



Inspect connector X109 before disconnection. Terminal A5, motor circuit (1552) is visibly backed out in the image above.



3272312

The same X109 terminal A5 visibly backed out in the image above.

## Warranty Information

For vehicle wiring harness repairs under warranty please use one of the following most appropriate labor operations.

Labor Operation	Description	Labor Time
N6650	Terminal Replacement	Use Published Labor Operation Time
N6655	Harness Replacement	Use Published Labor Operation Time
N6654	Connector Reconnection	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.