

NUMBER: 23-030-13

GROUP: Body

DATE: August 28, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

Clicking And/Or Ratcheting Sound When Operating The Right And/Or Left Door Glass

OVERVIEW:

This bulletin involves inspecting and if necessary replacing the right and/or left window regulator.

MODELS:

2003-2010

(ZB)

Viper

SYMPTOM/CONDITION:

Clicking and/or ratcheting sound when operating the right and/or left door glass.

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	04865610AH	REGULATOR, Right Front Door Window
1 (AR)	04865611AH	REGULATOR, Left Front Door Window

REPAIR PROCEDURE:

- 1. Cycle the left and right side door glass up and down. Did a ratcheting and/or clicking sound occur when the glass was all the way up or down?
 - a. Yes>>> Remove and replace the window regulator. Refer to the detailed repair procedures available in: DealerConnect> TechCONNECT under: Service Info> 23-Body> Door-Front> Regulator, Window> Removal/Installation.
 - b. No>>> Proceed to Step #3.
- 2. Return the vehicle to the customer.
- 3. Did a scraping sound occur only during a portion of up down travel in the middle of cycle?
 - a. Yes>>> Adjust the jack screws. Refer to the detailed adjustment procedures available in: DealerConnect> TechCONNECT under: Service Info> 23-Body> Door-Front> Glass, Door> Adjustments> Top of glass - inboard/outboard adjustments and return the vehicle to the customer.
 - b. No>>> Continue further diagnosis, this bulletin does not apply.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-34-10-B5	Cycle the right and left door glass only (1- Semi-Skilled)	6- Electrical and Body Systems	0.2 Hrs.
23-34-10-B6	Inspect the right and left window regulator operation and replace one side only (1-Semi-Skilled).	6- Electrical and Body Systems	0.8 Hrs.
23-34-10-B7	Inspect the right and left window regulator operation and replace both sides only (1-Semi-Skilled).	6- Electrical and Body Systems	1.3 Hrs.
23-34-10-B8	Inspect the right and left window regulator operation and adjust the jack screws, one side only (1- Semi-Skilled).	6- Electrical and Body Systems	0.4 Hrs.
23-34-10-B9	Inspect the right and left window regulator operation and adjust the jack screws, both sides(1- Semi-Skilled).	6- Electrical and Body Systems	0.6 Hrs.

FAILURE CODE:

ZZ	Service Action	9
----	----------------	---