

| Model(s) | Year(s) | Eng. Code(s) | Trans. Code(s) | VIN Range From | VIN Range To |
|----------|---------|--------------------|-------------------|----------------|--------------|
| Passat | 2012 | 2.0L TDI (CKRA) | DSG (02E) | All | All |
| Passat | 2012 | 2.0L TDI (CKRA) | Manual (02Q) | All | All |

Condition

01 13 03 January 25, 2013 **2030453** Supersedes T. B. V011228 dated October 2, 2012 to remove DTC P2201 applicability.

Update Programming MIL ON, DTCs P050E, P2080, P244C and/or P2478 Stored in ECM Fault Memory MIL ON Exhaust Gas Temperature Sensor faults P050E, P2080, P244C and/or P2478 stored in fault memory.



If diagnosing P2201 NOx Sensor Circuit Range/Performance Bank 1 Sensor 1, refer to technical bulletin 2032137.

Technical Background

Diagnostic strategy too sensitive.

Production Solution

Improved software implemented for model year 2013.

Dos Auto

Technical Bulletin

Service



DO NOT diagnose or replace any parts before performing the update function as explained in this bulletin.

One or more of the following fault codes may be stored in the ECM Fault Memory:

| Fault Code | Fault Description | | |
|------------|--|--|--|
| P050E | Cold Start Engine Exhaust Temperature Too Low | | |
| P2080 | Exhaust Gas Temperature Sensor Circuit Bank1 Range/Performance | | |
| P2478 | Exhaust Gas Temperature Out of Range Bank 1 Sensor 1 | | |
| P244C | Exhaust Temperature Too Low For Particulate Filter Regeneration Bank 1 | | |



To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.



Prior to launching VAS-PC application and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VVT-12-02. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.

When using a VAS 6150/5051B or VAS 5052A tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.



Update the Engine Control Module using the SVM Unit code as listed in the table below:

| Model | Engine | Old Software Part No. | Old Software Version | New Software Part No. | New Software Version (or higher) | SVM Unit Code |
|--------|--|--------------------------|---|--------------------------|---|------------------|
| Passat | 2.0L TDI (CKRA) With DSG (02E) | 03L906012BP | 1784, 2158 2939, 3866 | 03L906012BP | 4270 | 35F3 |
| Passat | 2.0L TDI (CKRA) With Manual (02Q) | 03L906012 | 0308, 0759 1012, 1783 2157, 2938, 3865 | 03L906012 | 4269 | 35F3 |

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



WARNING.

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.

Page 3 of 5 plus attachment



Warranty

| To determine if this Procedures Manual | | ered under War | ranty, always re | fer to th | ne Warranty P | olicies and | |
|---|------------------------------|--------------------|-----------------------|-----------|--|--|--|
| Model(s) | Year(s) | Eng. Code(s) | Trans. VIN Range F | | Range From | VIN Range To | |
| Passat | 2012 | 2.0L TDI (CKRA) | DSG (02E) | | All | All | |
| Passat | 2012 | 2.0L TDI (CKRA) | Manual (02Q) | All | | All | |
| | | SAGA | Coding | | | | |
| Claim Type: | Use applicable Claim Type 1) | | | | | | |
| Service Number: | Damage Code | | нѕт | | Damage Location (Depends on Service No.) | | |
| 2360 | 0039 | | | | | Use applicable when indicated in ElsaWeb (L/R) | |
| Parts Manufacturer | Passat TX6 | | | | TX6 ²⁾ | | |
| Labor Operation 3): Charge Battery | | | 27068950 = 10 TU | | | | |
| Labor Operation 3): Update EDC Program 2 | | | 23602599 = 60 TU | | | | |
| | | Diagnost | ic Time ⁴⁾ | | | | |
| GFF Time expenditure 01500000 = 20 | | | TU max. | | | YES | |
| Road Test 01210002 01210004 | | | | | | NO | |
| Technical Diagnosis 01320000 = 00 | | |) TU max. | | | NO | |
| Claim Comment: Inp | ut "As per Techn | ical Bulletin 203 | 30453" in comm | ent sec | tion of Warra | nty Claim. | |

¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.

⁴⁾ Documentation required per Warranty Policy Procedures Manual.



Required Parts and Tools

No Special Parts required.

| Tool Description | Tool No: |
|-----------------------------------|---|
| Midtronics Battery Tester/Charger | InCharge 940 (INC-940) |
| VAS Diagnostic Tool | VAS-PC, 5051B, 5052A, 6150X |
| | (Base CD V19.01.00 and Brand DVD V19.19.00 or higher) |

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

| *) "TUNING" is described as the addition of or modification of any cor Volkswagen vehicle to perform outside the normal parameters and sp Volkswagen Group of America / Volkswagen Group Canada. | |
|---|---------------------------|
| Date: | |
| Dealer Number: | |
| Vehicle Identification Number: | |
| Repair Order Number: | |
| | Dealer stamp |
| I, owner or driver of the above identified | |
| "Tuning" as described above (especially power increasing modifiperformed on my vehicle. | |
| Tuning" as described above has been performed on my vehicle and were modified or installed: | the following components |
| TUNING was performed by (Please provide Company name and telepho to contact them): | ne number, if you wish us |
| I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions conseque by VWGoA / VGC warranties. | |
| I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (d delete any tuning program that was previously installed on the Control M vehicle. | estroy) and permanently |
| By signing below, I fully acknowledge and understand that the tuning pro and VWGoA / VGC, will not be liable in any way for the loss of tuning da | |
| Signature | of Customer |