



# Technical Bulletin

Model(s)	Year	Engine Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Jetta Wagon	2009	2.5L (CBTA / CBUA)	All	1K_9M000001	1K_9M048611
Rabbit	2009	2.5L (CBTA / CBUA)	All	All	All

## Condition

01 13 34 October 24, 2013 2018902 Supersedes Technical Bulletin V010829 dated Oct. 22, 2008 due to updated SVM Unit Code, service procedure and revised warranty table.

Update Programming ECM for AC Cooling Efficiency



**Note:**

The condition as described does not compromise operator visibility.

**DO NOT** diagnose or replace components due to A/C Performance **BEFORE** performing the update function as explained in this bulletin.

## Technical Background

The A/C compressor will shut off too early under very light acceleration. This condition may lead to insufficient cooling efficiency in hot weather climates.

## Production Solution

Software updated as of VIN: 1K\_9M048612 for Jetta vehicles, Concern identified after end of production for Rabbit vehicles.

Affected ECM part numbers:

07K 906 055 M, N, P, Q

# Technical Bulletin

---

## Service

### Update-Programming Procedure:



#### Tip:

To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.



#### Note:

Prior to launching the VAS-PC and ODIS service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VVT-12-02. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.

When using a VAS 6150/5051B or VAS 5052A tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

**Critical Warning:** The Midtronics Battery Charger **must** be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.

# Technical Bulletin

- Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
Jetta/ Rabbit	2.5L (CBUA)	07K906055M	All	07K906055M	3859	3565
Jetta/ Rabbit	2.5L (CBUA)	07K906055N	All	07K906055N	3860	3565
Jetta/ Rabbit	2.5L (CBTA)	07K906055P	All	07K906055P	3861	3565
Jetta/ Rabbit	2.5L (CBTA)	07K906055Q	All	07K906055Q	3862	3565

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



**Tip:**

Upon completion of software update, verify Cruise Control function (if originally equipped) is activated via GFF Function Test Plan 01 – Activate/Deactivate Cruise Control System.



**WARNING:**

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



**Tip:**

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



# Technical Bulletin

## Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta, Jetta Wagon	2009	2.5L (CBTA / CBUA)	All	1K_9M000001	1K_9M048611
Rabbit	2009	2.5L (CBTA / CBUA)	All	All	All
<b>SAGA Coding</b>					
Claim Type:			Use applicable Claim Type <sup>1)</sup>		
Service Number:	Damage Code	HST	Damage Location (Depends on Service No.)		
2470	0039	--	Use applicable when indicated in ElsaWeb (L/R)		
Parts Manufacturer	Jetta, Jetta SportWagen		3ME <sup>2)</sup>		
	Rabbit		WVO <sup>2)</sup>		
Labor Operation <sup>3)</sup> : Charge Battery			27068950 = 10 TU		
Labor Operation <sup>3)</sup> : Update Programming			24702599 = 35 TU		
Causal Part: Select Labor Operation			24702599		
<b>Diagnostic Time <sup>4)</sup></b>					
GFF Time expenditure	01500000 = 00 TU max.			NO	
Road Test	01210004 = 10 TU			YES	
Technical Diagnosis	01320000 = 00 TU max.			NO	



# Technical Bulletin

**Claim Comment: Input “As per Technical Bulletin 2018902” in comment section of Warranty Claim.**

- <sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only**
- <sup>2)</sup> Code per warranty vendor code policy.**
- <sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.**
- <sup>4)</sup> Documentation required per Warranty Policy & Procedures Manual.**

## Required Parts and Tools

No Special Parts required.

<b>Tool Description</b>	<b>Tool No:</b>
<b>Midtronics Battery Tester/Charger</b>	<b>InCharge 940 (INC-940)</b>
<b>VAS Diagnostic Tool</b>	<b>VAS 5051B, VAS 5052A, VAS 6150/X &amp; VAS 6160/X with: ODIS Service 2.0.0 or higher with current online updates</b>

## Additional Information


**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**



**OWNER INFORMATION ABOUT CONTROL MODULE TUNING\*  
ACKNOWLEDGEMENT AND AUTHORIZATION FOR  
REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)**

\*) "TUNING" is described as the addition of or modification of any component which causes a Volkswagen vehicle to perform outside the normal parameters and specifications approved by Volkswagen Group of America / Volkswagen Group Canada.

Date: \_\_\_\_\_  
Dealer Number: \_\_\_\_\_  
Vehicle Identification Number: \_\_\_\_\_  
Repair Order Number: \_\_\_\_\_



Dealer stamp

I \_\_\_\_\_, owner or driver of the above identified Volkswagen, confirm:

- "Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.
- "Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

\_\_\_\_\_  
\_\_\_\_\_  
TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):  
\_\_\_\_\_

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by VWGoA / VGC warranties.

I am permitting an authorized Volkswagen Dealer to reflash (update) my Control Module, and by doing so, I understand that this process will automatically overwrite (destroy) and permanently delete any tuning program that was previously installed on the Control Module of my Volkswagen vehicle.

By signing below, I fully acknowledge and understand that the tuning program will not be restored and VWGoA / VGC, will not be liable in any way for the loss of tuning data.

\_\_\_\_\_  
Signature of Customer