

**NUMBER:** 14-002-13 REV. A

**GROUP:** Fuel System

**DATE:** March 13, 2013

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 14-002-13, DATED JANUARY 30, 2013, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE THE ADDITIONAL STEP TO REMOVE AND DISCARD THE EVAPORATIVE FILTER AND TUBE FROM THE FUEL FILLER HOSE.**

**SUBJECT:**

Fuel Spit Back During Refueling Due To Inlet Check Valve (X48 Lifetime Warranty Extension)

**OVERVIEW:**

This bulletin involves replacing the fuel filler tube if the condition occurs.

**NOTE: When removing the existing fuel filler tube note how it comes out to aid in installation of the new part.**

**MODELS:**

2005 - 2006 (HB) Durango

**NOTE: This Extended Warranty Bulletin applies to vehicles equipped with a gasoline engine built between December 1, 2004 (MDH 1201XX) and January 31, 2006 (MDH0131XX).**

**SYMPTOM/CONDITION:**

Some customers may experience a fuel spit back condition during a refueling event.

**DIAGNOSIS:**

If the customer experiences the symptom/condition, proceed to the repair procedure.


**PARTS REQUIRED:**

Qty.	Part No.	Description
AR (1)	CNNZX390AA	Tube, Fuel Filler
AR	6500911	Rivet, Splash Shield Attaching <b>**Maximum 5 rivets**</b>

**REPAIR PROCEDURE:**

**NOTE: When removing the existing fuel filler tube note how it comes out to aid in installation of the new part.**

1. **\*\*The new fuel filler tube (p/n CNNZX390AA) has an evaporative emission hose and filter assembly attached to the filler neck (Fig. 1) that will not be used in this repair. Cut the four tie straps that secure the evaporative filter and hose to the new fuel filler tube. Remove and discard the evaporative filter and hose.\*\***
2. On new fuel filler tube verify and write down existing torque (Fig. 1).



**Fig. 1 Fuel Filler Tube**

- 1 - Evaporative Emission Filter Retaining Tie Straps - Four Straps
- 2 - Evaporative Emission Filter and Hose Assembly
- 3 - Worm Gear Hose Clamp

---

**CAUTION: Protect Paint and Quarter panel metal during removal and installation.**

**NOTE: It may be necessary to loosen the worm gear hose clamp and rotate to allow the fuel filler neck to fit between the body and frame. If clamp is loosened then once installed re-torque to noted value.**

3. Hoist vehicle.
4. Remove Left rear wheel.
5. Remove the left quarter panel splash shield.
6. Replace the fuel filler tube, Following the detailed procedures found in DealerCONNECT>TechCONNECT Service Info > 14 - Fuel System> Fuel Delivery > Tube, Fuel Filler removal and installation procedures.
7. Install the left quarter panel splash shield. There are 5 plastic retaining rivets.
8. Install left rear wheel.

**POLICY:**

Reimbursable within the provisions of the warranty.

**NOTE: Vehicles included in this Service Bulletin have a lifetime warranty for this repair. See Warranty Bulletins; U.S. D-13-09, Canada SAB 2013-05, International ID-13-03 for details associated with the extended warranty.**

***TIME ALLOWANCE:***

<b>Labor Operation No:</b>	<b>Description</b>	<b>Amount</b>
14-60-15-96	Tube, Fuel Filler Replace (C) (2 - Skilled)	0.7 Hrs.

***FAILURE CODE:***

ZZ	Service Action
----	----------------