

Service Bulletin

File in Section: 01 - HVAC

Bulletin No.: 09-01-39-007B

Date: June, 2013

TECHNICAL

Subject: Carpet Wet When A/C is On (Realign A/C Drain Tube)

Models: 2011-2013 Chevrolet Caprice PPV

2008-2009 Pontiac G8


This bulletin is being revised to add the 2013 Caprice PPV. Please discard Corporate Bulletin Number 09-01-39-007A.

Condition

Some customers may comment that when the A/C is on, they feel moisture on the front floor carpet.

Cause

Example of a Collapsed A/C Drain Grommet



2321888

This condition may be caused by a collapsed A/C drain grommet (1), resulting in a wet carpet condition.

Correction

Remove the panels in order to gain access to the A/C drain pass-thru grommet and realign the drain tube using the procedure listed below.

1. Verify the customer condition.



2321478

- Remove the insulator panel (1). Refer to Instrument Panel Insulator Panel Replacement - Left Side in SI.
- 3. Remove the knee bolster (2).
 - Grasp the knee bolster assembly (2) and carefully pull downward to disengage the retaining clips.


Important: When removing the knee bolster, care must be taken not to scratch the steering column cover. This can be achieved by slightly bending the knee bolster to avoid contact with the steering column.

 Disconnect the headlamp switch electrical connector from the headlamp switch. Page 2 June, 2013 Bulletin No.: 09-01-39-007B



2321482

4. Remove the center console extension panel.



2321466


5. Remove the console trim plate (1).



2321480

Push the carpet down with one hand, and with the other hand, take a pick tool and insert the tool in the grommet.

Important: When installing the HVAC drain tube and grommet, make sure they are properly aligned in order to allow the HVAC water to drain properly.



2321517

- 7. Route the pick around the rubber HVAC drain grommet and make sure the drain tube is properly centered in the grommet. View the figure above and note how the HVAC drain tube grommet is positioned. The lip of drain grommet should be positioned inward of the entire circumference (1).
- 8. Reinstall all of the panels.
- 9. Let the vehicle run with the A/C on.
- 10. Perform a final inspection for the A/C and verify that the system is draining properly.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4480048*	Reinstall the HVAC Drain Grommet & Make Sure HVAC Drains	0.4 hr
·-· · · ·		1 1/ 11/

^{*}This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.