

TECHNICAL BULLETIN  
LTB00536NAS1  
10 MAY 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 413-01**

Front Parking Aid Tone Does Not Operate

**AFFECTED VEHICLE RANGE:**

LR4 (LA)	<b>Model Year:</b>	<b>2010-2011</b>
	<b>VIN:</b>	<b>AA510742-BA596987</b>
Range Rover Sport (LS)	<b>Model Year:</b>	<b>2010-2011</b>
	<b>VIN:</b>	<b>AA212147-BA717165</b>

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** The front parking aid tone may not operate.

**Cause:** This may be caused by a software issue.

**Action:** In the event of a customer concern of the above, refer to the Repair Procedure outlined below.

**PARTS:**

No Parts Required

**TOOLS:**

 **NOTE: This document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.**

IDS with latest IDS-DVD and Calibration File; first available on  
DVD133.04 v.130  
Jaguar Land Rover-approved Midtronics Vehicle Power Supply

**WARRANTY:**

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Software download - instrument pack - LR4	<b>88.90.04</b>	0.20	42	LR027892

Software download - instrument pack - Range Rover Sport	<b>88.90.04</b>	0.20	42	LR027898
---	-----------------	------	----	----------



**NOTE: Normal Warranty policies and procedures apply.**

### **REPAIR PROCEDURE:**

1. **CAUTION: Ensure all ignition 'ON' / ignition 'OFF' requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.**



**CAUTION: A Jaguar Land Rover-approved Midtronics Vehicle Power Supply must be connected to the vehicle battery during IDS / SDD diagnosis / module programming.**



**NOTE: IDS must be loaded with DVD133.04 v.130 or later.**

Connect the Jaguar Land Rover-approved Midtronics Vehicle Power Supply to the vehicle battery.

2. Turn ignition 'ON' (engine not running).
3. Connect the Integrated Diagnostic System (IDS) to the vehicle and begin a new Symptom Driven Diagnostics (SDD) session.
4. Follow the on-screen prompts, allowing SDD to read the VIN and identify the vehicle.
5. Select 'Diagnosis' from the Session Type screen.
6. Select the 'Selected Symptoms' tab, and then select the following:
  - Electrical > Driving aids > Parking aid > Front inoperative
7. Select the 'Recommendations' tab.
8. Select 'continue'.
9. From the Recommendations tab, select '**Run**' to perform the 'Configure existing module – Instrument cluster control module' option.
10. Follow all on-screen instructions to complete this task.
11. Exit the current session.
12. Disconnect the IDS and the vehicle power supply from the vehicle.