

TECHNICAL BULLETIN  
LTB00605NAS1  
19 NOV 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 501-10**

Front Seatback Tilt Lever Inoperative

**AFFECTED VEHICLE RANGE:**

**Range Rover Evoque (LV)**

**Model Year:** 2012-2013

**VIN:** CH000447-DH856574

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** On Range Rover Evoque Coupe vehicles fitted with standard (non-sport) seats only, the front seatback tilt lever may be difficult to operate.

**Cause:** This may be caused by the tilt release mechanism within the seatback frame assembly being stiff or 'notchy'.

**Action:** Should a customer express this concern, follow the Service Instruction outlined below.

**PARTS:**

LR057581      Seat frame - LH/RH      Quantity: 1

**TOOLS:**

Refer to Workshop Manual for any required special tools.

**WARRANTY:**



**NOTE: If both front seats are affected, repair each seat according to the repair times provided. An EPQR with associated videos capturing the defect should be forwarded as evidence.**



**NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**



**NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Check functionality of front seats	<b>05.10.10</b>	0.1	41	LR047054
Frame assembly - Seatback - Front seat - LH - Renew	<b>78.85.11</b>	1.0	41	LR047054
Frame assembly - Seatback - Front seat - RH - Renew	<b>78.85.12</b>	1.0	41	LR047054





**NOTE: Normal Warranty policies and procedures apply.**

### **SERVICE INSTRUCTION:**

1.  **NOTE: Front right seatback shown; front left seatback similar.**

Lift the front right seatback locking lever and pivot the seatback forwards; make sure that there is no contact between the front edge of the lever and the bezel when the lever is lifted.

- If no contact between the lever and bezel is evident or the seatback does not release, continue to step 2.
- If contact between the lever and bezel is evident, replace the lever. To be performed as a separate claim.



2. Lift the front seatback locking lever and check for cable disconnection:

- Make sure that the silver cable end is in the correct position on the lever.
- If the cable is not properly retained, remove the lever and check for damage.
  - If damage is evident, replace the lever. To be performed as a separate claim.
  - If no damage is evident, re-fit the lever.



3. If no fault is found in steps 1 or 2 and the lever is difficult to operate or 'notchy', install a new seatback frame (see TOPIX Workshop Manual, Section 501-10).

4. Repeat steps 1-3 to the front left seat.