

TECHNICAL BULLETIN
LTB00613NAS1
15 NOV 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 413-01

Instrument Cluster Software Service Update

AFFECTED VEHICLE RANGE:

Range Rover (LG)

Model Year: 2013

VIN: DA001204-DA124981

MARKETS:

NAS

CONDITION SUMMARY:

Situation: Following an engine start, the primary and/or secondary airbag warning lamp may be displayed and then extinguishes at the next ignition cycle. Diagnostic Trouble Code (DTC) B1A14-96 will also be stored in the Instrument Cluster.

Cause: This may be caused by intermittent primary airbag fault detection within the Instrument Cluster.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

No Parts Required

TOOLS:



NOTE: This document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.

SDD with latest DVD and Calibration File; first available on DVD135.06 v.150
Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.



NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Update Instrument Cluster software	88.90.03	0.7	42	LR033681



NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.  **CAUTION: A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during SDD diagnosis / module programming.**



NOTE: SDD must be loaded with DVD135.06 v.150 or later.

Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.

2. Turn ignition 'ON' (engine not running).
3. Connect the Symptom Driven Diagnostics (SDD) system to the vehicle and begin a new session.
4. Follow the on-screen prompts, allowing SDD to read the VIN and identify the vehicle and initiating the data collect sequence.
5. Select 'Diagnosis' from the Session Type screen.
6. Select the 'Selected Symptoms' tab, and then select the following:
 - Electrical - Instruments - Warning lamps - Airbag warning lamp
7. Select 'continue'.
8. Select the 'Recommendations' tab, and then select '**Run**' to perform the 'Configure existing module – Instrument cluster control module' option.
9. Follow all on-screen instructions to complete this task.
10. Exit the current session.
11. Disconnect the SDD and the battery power supply from the vehicle.