

TECHNICAL BULLETIN  
Q140NAS2  
31 OCT 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

Changes are highlighted in gray

**SECTION: 418-02**

Service Action: Rear View Camera 'Blue' Screen

**AFFECTED VEHICLE RANGE:**

**Range Rover (LM)**  
**Model Year:** 2010-2011  
**VIN:** AA302865-BA336802

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** A potential concern has been identified on a limited number of vehicles fitted with the Surround Camera System which may experience signal loss within the camera cables, resulting in a 'blue' screen being displayed.

**Action:** Retailers are required to **HOLD** all affected vehicles within the listed VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

**PARTS:**

DESCRIPTION	PART No.	QTY.	EXPECTED % of VEHICLES REQUIRING PARTS*
Parking aid camera signal filter	LR031215	1	100



**NOTE: \* when ordering parts, order only the expected percentage demand of parts identified**

**SPECIAL TOOLS:**

Refer to Workshop Manual / Service Instruction for any required tools

**WARRANTY:**



**NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to the Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate**

**workshop time is allocated for repairs to be completed at one visit.**

Warranty claims must be submitted quoting Program Code '**Q140**' together with the relevant Option Code from the table. The SRO and part information listed have been included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **30 April 2014** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS	QTY. / VALUE
Q140	B	Fit parking aid camera signal filter	86.71.89.37	0.30	LR031215	1
Q140	C	Fit parking aid camera signal filter Drive in/drive out	86.71.89.37 02.02.02	0.30 0.20	LR031215 -	1 -



**NOTE: Normal Warranty policies and procedures apply**

**SERVICE INSTRUCTION:**

1. Install a Parking Aid Camera signal filter (see TOPIx Workshop Manual, Section 418-02).