| | 001400000 |
|---------------|--|
| Reference | SSM69398 |
| Models | Range Rover (All New) / L405 Range Rover Sport / L494 |
| Title | No Communication with Chassis Control Modules after re- connecting battery. |
| Category | Chassis |
| Last modified | 06-Nov-2013 00:00:00 |
| Symptom | 304000 Suspension System |
| | Issue: |
| | If the battery supply to the vehicle is disconnected for any reason then either or both of the Chassis Control Modules may not power up correctly. As a result, the SDD service tool will report no communication with the CHCM and/or CHCMB modules. This will only affect a small percentage of parts and on an intermittent basis. The vehicle may also display error messages on the |
| | cluster relating to suspension and adaptive dynamics |
| | faults: • "SUSPENSION FAULT Vehicle Lean When Cornering" • "SUSPENSION FAULT Max Speed 30 MPH" • "Adaptive Dynamics Fault" |
| | The SDD tool may also log the following DTCs from modules which communicate with the CHCM and |
| | CHCMB: 12MX Papage Power L 405 |
| | <u>13MY Range Rover L405</u> Modules which receive CAN messages from the CHCMB module may log the following DTC |
| | • U012B-00 (C12B-00) - Lost Communication with |
| Content | Observice Ossitual Marchila "D" as such two sinformations |
| Content | Modules which receive CAN messages from the CHCM module may log the following DTC |
| | • U012A-00 (C12A-00) - Lost Communication with Chassis Control Module "A"-no sub type information |
| | <u>14MY Range Rover L405, Range Rover Sport 14MY L494</u> Modules which received CAN messages from the CHCM/CHCMB module may log the following DTC |
| | • U0001-87 (C001-87) - High Speed CAN Communication Bus - missing message |
| | <u>Cause:</u> The power up strategy currently in place for the CHCM and CHCMB can cause this concern. |
| | Action: To resolve the issue, fully disconnect the negative lead from the battery terminal. Wait for 5 minutes and re- connect the battery negative. Repeat this process if necessary. Ensure that a power supply unit is NOT connected to the vehicle when doing this. SDD should confirm communication with the CHCM and CHCMB (note: the CHCMB is optional) and cluster error messages will no longer appear. |