



Service Bulletin

File in Section: -

Bulletin No.: PIC5791

Date: January, 2013

PRELIMINARY INFORMATION

Subject: Service Power Steering DIC Message With DTC C0545

Models: 2013 Cadillac ATS

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

In rare situations a customer may comment that upon starting the engine, the DIC displayed a Service Power Steering message and experienced a loss of steering assist.

This condition would only occur immediately following an engine start just after turning off the ignition and must be combined with a low voltage condition such as that of a low battery. The Service Power Steering DIC message will come on.

If the customer shuts the Ignition Off, waits 15 seconds for the vehicle modules to go to sleep then restarts the engine, the concern will go away.

The Power Steering Control Module (PSCM) will have stored DTC C0545 Symptom Code 00.

Note: It may be difficult for the dealer to reproduce this concern.

Recommendation/Instructions

SPS program the PSCM through TIS2WEB with the latest calibrations available. Follow SI procedures for SPS Programming and Configuration of the module.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
E9450	Power Steering Control Module - Reprogram	0.4 hr

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.