



Service Bulletin

File in Section: -

Bulletin No.: PIC5796A

Date: February, 2013

PRELIMINARY INFORMATION

Subject: Intermittent No Heat In EV Electric Mode

Models: 2013 Chevrolet Volt

This PI was superseded to update for repair. Please discard PIC5796.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customer may state that they have no heat in EV electric mode at times. The customer states that the heat will be ok when in charge sustaining mode (engine on) and the concern usually goes away after you power down the vehicle and let it sit for 4-5 minutes with the ignition off. The concern is very infrequent and may not return again.

Recommendation/Instructions

Important: This only applies to the vehicle if the concern is intermittent. If the concern is there all the time, please follow normal diagnosis in SI. Please don't replace any HVAC components including any coolant pumps or valves.

Engineering has released an updated calibration. Please update the K33 HVAC Control Module with the latest calibration in TIS-2-Web.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
D4707	HVAC Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.