



Service Bulletin

File in Section: -

Bulletin No.: PI1128

Date: December, 2013

PRELIMINARY INFORMATION

Subject: Rub, Scuff or Squeak Noise from Right Rear Wheel Area at Slow Speeds

Models: 2012-2014 Chevrolet Equinox
2012-2014 GMC Terrain

Condition/Concern

Some customers may comment on a rub, scuff or squeak type noise heard from the right rear wheel area after the vehicle is fully warmed up and at very slow speeds. Light brake apply may affect the noise level.

This condition may be caused by the wheel bearing and hub seal.

Recommendation/Instructions

If the noise is confirmed to be from the right rear hub, replace the right rear wheel bearing/hub assembly. Refer to the Rear Wheel Bearing and Hub Replacement procedure in SI.

Parts Information

Part Number	Description	Qty
25979186	Right Rear Wheel Bearing/Hub Assembly	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8041250	Rear Wheel Bearing and Hub Replacement	Use Published Labor Operation Time