

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan

Service Category Engine/Hybrid System

Section Hybrid/Battery Control System

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2012	Camry HV	

Introduction

Some 2012 model year Camry HV vehicles may exhibit a MIL "ON" condition with Diagnostic Trouble Code (DTC) P0A80 or P0A7F stored due to dust or debris build-up in the HV Battery Cooling Fan. Use the following repair procedure to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL1308	Clean HV Battery Cooling Fan, Replace HV Battery Assembly, Install HV Battery Cooling Fan Intake Filter, and Reprogram Power Management ECU	2.6	G9510-33050	8A	99

APPLICABLE WARRANTY

- This repair is covered under the Toyota Hybrid System Warranty. This warranty is in effect for 96 months or 100,000 miles, whichever occurs first, from the vehicle's in-service date.
- For California specification vehicles sold, registered, and operated in Arizona, California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New York, Oregon, Rhode Island, or Vermont, this repair is covered under the California Emission Warranty, for 120 months or 150,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan

Calibration Information

MODEL	ECM (CPU)	CALIBRATION ID		VDS
		PREVIOUS	NEW	
Camry HV LE	Power Management ECU	896B30601000	<u>896B30601200</u>	BD1FK
		896B30601100		
Camry HV XLE		896B53301000	<u>896B53301100</u>	BD1FK
	896B30603000	<u>896B30603100</u>		

Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
89690-06010 89690-06011 89690-06030	89690-06012 89690-06031	Power Management Control ECU	-
G92DH-33020		Filter, HV Battery Intake, No. 1	1
G9510-33050		Battery Assembly, HV Supply	1
00451-00001-LBL		Authorized Modification Label	1

NOTE

- The Power Management ECU should NOT be replaced as part of the repair procedure.
- Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through *Dealer Daily – Dealer Support Materials Orders*.

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan

Required Tools & Equipment


SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	<u>00002-MCGR8</u>	1
Electrical Insulating Gloves*	<u>00002-03100-S</u> (Small)	1
	<u>00002-03200-M</u> (Medium)	
	<u>00002-03300-L</u> (Large)	

NOTE
 Additional SSTs may be ordered by calling 1-800-933-8335.

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*	ADE	TS2UNIT	1
TIS Techstream		TSPKG1	
Techstream Lite		TSLITEDLR01	

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 8.20.019 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- The Diagnostic Tester is NOT recommended for flash reprogramming. Please use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit techinfo.toyota.com for more information regarding J2534 reprogramming.



* Essential SST.

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan**Repair Procedure**

1. Inspect the HV Battery Cooling Fan for dust or debris build-up.

Refer to the Technical Information System (TIS), 2012 Camry HV Repair Manual:

- *Engine/Hybrid System – Hybrid/Battery Control System – “Hybrid/Battery Control: Battery Blower: Removal”*


Is the HV Battery Cooling Fan clogged with dust or debris build-up? Refer to Figure 1 for an example of a clogged cooling fan.

- **YES** – Proceed to step 2.
- **NO** – This bulletin does NOT apply. Troubleshoot the vehicle using the Repair Manual procedure.

Refer to TIS, 2012 Camry HV Repair Manual:

Engine/Hybrid System – Hybrid/Battery Control System – “Hybrid/Battery Control: Hybrid Battery System: P0A80-123: Replace Hybrid Battery Pack / P0A7F-123: Hybrid Battery Pack Deterioration”

Figure 1.



2. Clean dust and debris build-up from the HV Battery Cooling Fan with compressed air or vacuum.

NOTICE

Do NOT allow the cooling fan to spin freely during cleaning. This may damage the cooling fan motor.

3. Replace the HV Battery Assembly.

Refer to TIS, 2012 Camry HV Repair Manual:

- *Engine/Hybrid System – Hybrid/Battery Control System – “Hybrid/Battery Control: HV Battery: Removal / Installation”*

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan


Repair Procedure (Continued)

4. Install the HV Battery Cooling Fan Intake Filter as shown.

NOTE

The filter should be cleaned when dust begins to appear on the surface.

Figure 2.




MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan

Repair Procedure (Continued)

5. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure 3. Confirm if the Power Management ECU calibration has been updated. If the calibration ID listed is NOT the latest Power Management ECU calibration — go to step 6.

Figure 3. Location of Authorized Modifications Label on 2012 Camry HV



1	Replacement ECU Part Number (i.e., 89690-06012)
2	New Calibration ID(s) (i.e., 896B30601200)
3	Dealer Code

4	Date Completed
5	This SB Number

MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in HV Battery Cooling Fan

Repair Procedure (Continued)

6. Flash reprogram the Power Management ECU.

NOTE

- The GR8 Battery Diagnostic Station **MUST** be used in Power Supply Mode to maintain battery voltage at 13.5 volts while flash reprogramming the vehicle.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the **GR8 Instruction Manual** located on the Technical Information System (TIS), ***Diagnosics – Tools & Equipment – Battery Diagnostics***.

Follow the procedures outlined in Service Bulletin T-SB-0012-13, "Techstream ECU Flash Reprogramming Procedure," and flash the Power Management ECU with the NEW calibration file update.

7. Install the Authorized Modifications Label.
 - A. Using a permanent marker, enter the following information on the label:
 - ECU part number [*Refer to the **Parts Information** section for the **NEW PART NUMBER***]
 - Calibration ID(s) [*Refer to the **Calibration Information** section for the **NEW CALIBRATION ID***]
 - Dealer Code
 - Repair Date
 - Change Authority [***This SB number***]
 - B. Affix the Authorized Modifications Label to the vehicle at the location shown in Figure 3. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.
8. Clear any DTCs that have set during the repair procedure and test drive the vehicle to confirm normal operation.
9. For severe usage vehicles, refer to Service Bulletin T-SB-0087-13, "HV Battery Cooling Fan Maintenance for Severe Usage Vehicles," for additional HV Battery Cooling Fan maintenance recommendations.

