Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2013 Mazda Motor of America, Inc.

 Subject:
 Bulletin No:
 01-001/13


 MIL ON WITH DTC P2610
 Last Issued:
 01/07/2013

APPLICABLE MODEL(S)/VINS

2014 Mazda6 2013-2014 CX-5

DESCRIPTION

Some vehicles may experience MIL illumination with DTC P2610 (Instrument cluster internal engine off timer performance problem) stored in memory after engine start and room fuse 15A (A) removed.



Vehicles in dealer inventory with this concern should be repaired using the following repair procedure.

REPAIR PROCEDURE

- 1. Verify DTC P2610 is stored in PCM memory.
- 2. With the ignition off, install ROOM fuse 15A.
- 3. Clear DTC P2610 from PCM memory using IDS.
- 4. Verify no other DTCs are stored in memory. If so, troubleshoot them according to the MS3 online instructions or Workshop Manual.

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.

Bulletin No: 01-001/13	Last Issued: 01/07/2013
© 2013 Mazda Motor of America, Inc.	

WARRANTY INFORMATION

NOTE:

This repair will be covered only while the vehicle is in Dealer New Car status.

• Additional diagnostic time cannot be claimed for this repair.

	CX-5	2014 Mazda6
Warranty Type	А	A
Symptom Code	6X	6X
Damage Code	9W	9W
Part Number Main Cause	KD45-66-76YA	GHP9-66-760
Quantity	0	0
Operation Number / Labor Hours:	XXH35XRX / 0.2 Hrs.	XXH35XRX / 0.2 Hrs.