

//ALL 10/20/2014 to 11/10/2014
TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: 10/20/2014
SUBJECT: Update Service Campaign TT9 - 2014-15 Elantra(UD) Overhead
Console Sunglass Holder Latch Replacement and Sunroof Motor Reset
(TSB# 14-01-036-1)

Hyundai Motor America has added additional vehicles to Service Campaign TT9. Service Campaign TT9 provides a procedure to replace the sunglass holder latch and resetting the sunroof motor which is required after the motor is disconnected during repair procedure.

In order to identify only those vehicles affected by Service Campaign TT9, it will be necessary to access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS before starting the repair. The "Warranty Vehicle Information" screen will identify affected vehicles with an open Service Campaign TT9.

A listing of VEHICLES is also located on WEBDCS, SERVICE tab, select INFORMATION, and select UNCOMPLETED CAMPAIGN VIN LISTING - DEALER STOCK AND RETAILED.

Updated TSB #14-01-036-1 is available on Hyundai's Website as of October 20, 2014. It contains instructions on performing the service and submitting the campaign claim.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this service campaign. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA