

**Subarunet Announcement**

**To: All Subaru Retailers**

**From: Subaru of America, Inc.**

**Date: August 11, 2014**

**Update: WQL-48 Front Passenger Air Bag Inflator Recall (NHTSA ID 14V-399)**

On July 3, 2014, Subaru of America, Inc. (SOA) announced that a defect, which relates to motor vehicle safety, may exist on the following potentially affected vehicles. The subject vehicles are equipped with front passenger air bag inflators which could have been assembled with improperly manufactured propellant wafers.

**Affected Vehicles**

This condition may exist on certain 2003-2004 model year Legacy, Outback, and Baja vehicles, and certain 2004 model year Impreza, WRX, and STI vehicles.

Model Year	Model	Starting production date	Ending production date
2003	Legacy	01/22/2003	05/14/2003
2004	Legacy	03/17/2003	02/10/2004
2003	Outback	02/18/2003	04/15/2003
2004	Outback	02/28/2003	02/11/2004
2003	Baja	01/22/2003	05/06/2003
2004	Baja	03/03/2003	07/21/2004
2004	Impreza, WRX, STI	01/08/2003	05/15/2003

Not all vehicles within these production date ranges are affected by this recall. The potentially affected vehicles were identified based on the serial number of the front passenger air bag inflator installed during vehicle production.

Coverage for all potentially affected vehicles must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com. This data will be available when owner notification begins.

**Description of the Safety Defect and Safety Hazard**

In the event of a crash necessitating deployment of the passenger side frontal air bag, improperly manufactured propellant wafers inside the inflator could cause the inflator to rupture with metal fragments striking and potentially seriously injuring the vehicle occupants.

**Description of the Remedy**

Although the percentage of affected vehicles is unknown, replacement of the vehicle's front passenger air bag inflator will be performed on all of the potentially affected vehicles.

**Retailer Program Responsibility**

Retailers are to promptly perform the applicable service procedures to correct all affected vehicles in their inventory (used, demo & SSLP). Additionally, whenever a vehicle subject to this recall is taken into retailer inventory, or in for service, necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

New, used, demo or SSLP vehicles listed in any recall/campaign that are in retailer stock must be:

- Immediately identified.
- Tagged or otherwise marked to prevent their delivery or use prior to inspection and/or repair.
- Repaired in accordance with the repair procedures outlined in the Product Campaign Bulletin

**Owner Notification**

Owner notification will begin on August 12, 2014. In addition to notification by mail, vehicle owners with a valid email address and MySubaru subscribers will be notified electronically on August 13, 2014. A copy of the owner notification letter is included at the end of the WQL-48 campaign bulletin.

Since owner notification will occur this week, retailers are requested to order parts to support scheduled customer service appointments. Retailer affected VIN Lists will be distributed by the Zone Offices.

### **Product Campaign Bulletin**

The WQL-48 product campaign bulletin is posted on the Subaru Technical Information System (STIS) website under "Information/What's New." Please refer to the bulletin for repair instructions and additional information including parts information, part return procedures, and claim submission instructions.

#### **IMPORTANT:**

Each removed air bag inflator must be returned directly to the supplier, Takata USA, in the same box in which the new one was received.

The shipping box contains a bar code with the serial number of the new air bag inflator, which will be used by Takata USA to document the replacement of the old inflator with the new inflator. **Therefore, it is very important that the removed inflator be returned in the exact same box that contained the newly-installed inflator for that vehicle.** If the original box cannot be re-used, please refer to the shipping instructions under "Requesting a new box/shipping labels."

Prepaid FedEx shipping documents and shipping instructions will be included with each new air bag inflator kit. A copy of this information is included as 'Appendix A' of the bulletin. A completed SOA Warranty Parts Tag (MSA5W402A) must be attached to the returned inflator. The tag must contain the following information: claim number, repair date, full 17-digit VIN, and mileage.

Takata USA has assigned each Subaru retailer a **ChemTrec Contract Number (CCN)**. As shown in step 5 of the shipping documentation instructions, the shipping retailer must fill in their name, address, and CCN.

ChemTrec is a company that provides 24-hour emergency response and information to hazardous material shippers. The assigned CCN allows the Subaru retailer to ship hazardous material as an affiliate to Takata USA's registration with ChemTrec. This number is required on the return shipping form.

As the shipper, you are responsible for proper packing and document completion. The person packaging the inflator must have received hazardous material training per 49CFR 172.702, and the training records must be on file at your dealership. The US Department of Transportation will impose substantial fines and/or penalties on the shipper if either packaging, labeling or documentation is not properly prepared and the Customer Copy of OP 900PRP form is not kept on file for a minimum of 2 years.

**IMPORTANT:** Do not deploy any inflator. Return the used inflator within 1-2 business days. The person packing the used inflator must read and follow the provided instructions.

A list of all Subaru retailers along with their assigned CCN information is included as 'Appendix B' of the bulletin. It is SOA's intention to include a copy of this list with each new air bag inflator kit. However, the first shipment of parts did not include this list as it was not available at the time the parts were packed by Takata. Future shipments will include this document for reference.

The CCN list included with future shipments will be updated periodically to include new Subaru retailer information. If a Subaru retailer is unable to find their CCN, they should contact Takata USA as described in step 5 of the shipping documentation instructions.

#### **SOA PART RETURN NOTICE**

Upon claim approval, Subaru of America, Inc. will generate a Part Return Notice **requesting information only**. To ensure proper claim credit, the following information must be recorded on the SOA Part Return Notice and sent to SOA Part Collection Center (PCC) as instructed on the return notice:

- The FedEx Shipper Receipt # (from shipping form)
- The OLD and NEW air bag inflator serial numbers

The Part Return Notice should then be returned using UPS 3<sup>rd</sup> party billing to the address listed at the bottom of the notice. Please keep the UPS tracking number for your records.

**Under no circumstances should the air bag inflator be returned to Subaru of America, Inc.**