


[tpms attachment.pdf](#)

Reference	SSM70638
Models	LR4 / L319 Range Rover Sport / L494 Range Rover (All New) / L405
Title	TPMS Sensor Not Operating Correctly When New Service Part Fitted
Category	Chassis
Last modified	06-Jan-2014 00:00:00
Symptom	306000 Tyres/Wheels
Content	<p>Note: For further information related to TPM sensor identification please see Technical bulletin LTB00611 Tire Pressure Monitoring System Communication Frequency Change</p> <p>Issue: From Vin LA696287, L319 LW319923, L494 LG140911 L405 When a new service part TPMS sensor is not functioning immediately after fitment , i.e. no learning, failure of wheel sensor test, react as if they are stuck in shipping mode. Regardless of any driving cycle the parts will never go into the correct working mode.</p> <p>Cause: Service parts have been delivered in the "wrong mode".</p> <p>Action: If a part is received in "ship mode" it must not to be used, and should be returned, any additional consequential parts or time incurred shoul be submitted under a parts warranty claim. Latest parts will be supplied correct mode i.e. in "park mode", this can be identified with a yellow dot on the part itself, and with "park mode" on the packing (see attachment.)</p> <p>Note: The part number LR058023 has not changed In markets where 433Mhz sensors have been historically used, the old part No. LR031712 may successfully be used as an alternative to LR058023, although this is not the prefered option. Part LR031712 must NOT be used in the following markets: American Samoa Aruba Bolivia Brazil Canada Cayman Islands Colombia Costa Rica Ecuador Guam</p>



Honduras
Hong Kong
Macau
Mexico
Panama
Paraguay
Puerto Rico
Seychelles
Singapore
Thailand
United States of America
Venezuela

