

TECHNICAL BULLETIN
Q275NAS3
11 APR 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

Changes are highlighted in gray

SECTION: 501-10

Service Action: Rear Seat Fold

AFFECTED VEHICLE RANGE:

Range Rover (LG)
Model Year: 2013
VIN: DA100499-DA114045

MARKETS:

NAS

CONDITION SUMMARY:



NOTE: This program has been reinstated with immediate effect.

Situation: Vehicles within the listed VIN range may have an issue with the rear seat fold operation when the vehicle is in power mode '0' (OFF) with the doors and tailgate open. In this state, the rear seat fold operating time is reduced from 10 minutes to 3 minutes.

Action: Retailers are required to **HOLD** all affected vehicles in the above VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

No parts required

SPECIAL TOOLS:



NOTE: This document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.

SDD with latest DVD and Calibration File; first available on DVD137.02 V.165

Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:

NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to the Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**Q275**' together with the relevant Option Code from the table. The SRO and part information listed have been included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 March 2015** expiry date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS	QTY. / VALUE
Q275	B	Update rear seat module software - One side	78.91.04.01	0.20	-	-
		Update rear seat module software - Second side with diagnostic equipment already connected	78.91.04.02	0.10	-	-
Q275	C	Update rear seat module software - One side	76.91.04.01	0.20	-	-
		Update rear seat module software - Second side with diagnostic equipment already connected	78.91.04.02	0.10	-	-
		Drive in/drive out	02.02.02	0.20	-	-



NOTE: Normal Warranty policies and procedures apply

SERVICE INSTRUCTION:

-  **CAUTION: Ensure all ignition 'ON' / ignition 'OFF' requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.**



CAUTION: A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during SDD diagnosis / module programming.



NOTE: SDD must be loaded with DVD137.02 v.165 or later.

Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.

- Turn ignition 'ON' (engine not running).
- Connect the Symptom Driven Diagnostics (SDD) system to the vehicle and begin a new session.

4. Follow the on-screen prompts, allowing SDD to read the VIN and identify the vehicle and initiating the data collect sequence.
5. Select 'Diagnosis' from the Session Type screen.
6. Select the 'Selected Symptoms' tab, and then select the following:
 - Body > Seating > Rear right seat
7. Select the 'Extras' tab.
8. From the Recommendations tab, select **Run** to perform the 'Configure existing module – Rear seat - Control module - Right' option.
9. Follow all on-screen instructions to complete this task.
10. Select the 'Selected Symptoms' tab, and then select the following:
 - Body > Seating > Rear left seat
11. Select the 'Extras' tab.
12. From the Recommendations tab, select **Run** to perform the 'Configure existing module – Rear seat - Control module - Left' option.
13. Follow all on-screen instructions to complete this task.
14. Exit the current session.
15. Disconnect the SDD and the battery power supply from the vehicle.