

Reference	SSM61017
Models	LR2 / L359
Title	LR2 / Freelander 2 – click noise from drive shafts / half shafts
Category	Driveline
Last modified	22-Aug-2014 00:00:00
Symptom	597997 Driveline Noise Concerns
Attachments	pic12.pdf
Content	<p>Issue: The customer reports a click noise while manoeuvring at low speeds – LR2 / Freelander 2 only. The issue is identified as a click noise from a front drive shaft (half shaft).</p> <p>Cause: Small amount of movement of the splines of the shaft within the hub.</p> <p>Action:</p> <ul style="list-style-type: none">• Remove the LH and RH outboard joints, (see Global Technical Reference GTR Workshop Manual, section: 205-04) .• 2. Apply a bead of loctite 638 high strength retainer, to driveshaft as shown in attached file (pic1.pdf).• Install the LH and RH outboard joints (see Global Technical Reference GTR Workshop Manual, section: 205-04).