

# **Short Pin Installation During PDS**

 Service Category
 General
 Toyota Supports

 Section
 Pre-Delivery Service
 Market
 USA

#### Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2015	Camry, Camry HV	

#### Introduction

To minimize battery discharge during transportation and storage, the Short Pin has been removed at the assembly plant and temporarily stored in the engine compartment Relay Block. Reinstall the Short Pin into its original location and confirm all related DTCs are cleared during Pre-Delivery Service (PDS).

#### NOTE

The short pin is removed only on vehicles going to Hawaii, Puerto Rico, Saipan, Guam and American Samoa.

#### **Required Tools & Equipment**

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*		TS2UNIT	1
Techstream Lite	ADE	TSLITEPDLR01	

\* Essential SST.

#### NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 9.20.022 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

#### Warranty Information


OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	_	_	-	-

## **Short Pin Installation During PDS**

#### Installation Procedure

Remove the Short Pin from the blank space of the Relay Block in the engine compartment and install the Short Pin in the Relay Block as shown.

Figure 1.



### NOTE

- The Short Pin does NOT function as a fuse, so install it only in the position shown.
- If the vehicle is stored in the dealership after PDS, disconnect the negative (–) battery terminal to prevent battery discharge. Refer to Service Bulletin No. <u>PG001-06</u>, "Battery Maintenance for In-Stock Vehicles & Pre-Delivery".

#### **DTC Clearing Procedure**

With the Short Pin removed, the occupant classification ECU and Center Airbag Sensor Assembly (airbag ECU) may detect the interruption in battery voltage (B+) and store a DTC. Clear DTCs B1650 and B1794 after installing the Short Pin.

- 1. Connect TIS Techstream to DLC3.
- 2. Cycle the ignition switch to the "IG-ON" position.
- 3. Using TIS Techstream, check any other codes being output.

#### NOTE

If any DTCs besides B1650 and B1794 remain, repair the applicable system according to the Repair Manual.

4. Erase DTCs (B1650 and B1794) and Freeze Frame Data.