



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Steering Pulls To The Right At Highway Speeds

**Models:** 2014 Chevrolet Corvette

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment that the vehicle steering pulls to the right while trying to maintain a straight line heading at highway speeds. The pull is correctable.

**Note:** If the vehicle drives straight ahead without a pull/drift but the steering wheel is off-angle, then this is a steering wheel angle concern for which this PI does not apply; refer to the Steering Wheel Angle and/or Front Toe Adjustment procedure in SI to correct a steering wheel angle concern.

### Recommendation/Instructions

**Note:** Be sure to capture "Before" and "After" wheel alignment measurements whenever an alignment is performed.

1. The pull can be minor, but still correctable. Verify that this is a pull condition by lightly holding the steering wheel while driving the vehicle in a straight line at 60-65MPH. Hold the steering wheel "lightly" so as to notice if the car has a tendency to drift or pull to one side of the lane or the other. Document the direction of the pull / drift and rate the condition by describing the amount of pull / drift on a scale of 1-10, with 10 being no pull / drift and 1 being a severe pull. Do this evaluation in both left and right sloping lanes as the vehicle will follow the road crown/camber.

**Note:** If the vehicle follows the road crown/camber, this is normal operation and the vehicle is performing to design intent. As such, do NOT perform the following steps.

2. Do a Left to Right front wheel/tire assembly swap then evaluate the vehicle for pull / drift as in step 1 and document the results. If the pull / drift direction is opposite, then follow the Radial Tire Lead/Pull correction procedure noted in SI to isolate the tire causing the concern. Otherwise, continue to next step if pull / drift in the same direction is still present.
3. Put the vehicle on an alignment rack. Record the "Before" measurements and modify the wheel alignment to counteract the pull or drift condition. Assuming cross-camber is not causing the right pull / drift concern by being near the negative limit noted in SI, begin by increasing caster on the right and/or /decreasing caster on the left. Try to stay within the current wheel alignment specifications in SI, however, if necessary, you may use cross-caster down to or as far negative as -1.0 degrees (which is currently outside the specifications noted in SI). Split the left and right caster about the current nominal caster values noted in SI by increasing one side of the vehicle by the same amount decreased on the other side. Strive to remain within the wheel alignment specifications noted in SI and this PI. Evaluate vehicle for pull in both left and right sloping road crown/camber road conditions and verify normal operation mentioned in step 1. Record the "After" wheel alignment measurements to include with the "Before" measurements for the warranty claim.
4. If, after exhausting standard Vehicle Leads/Pulls diagnostics and the above steps, a pull to the right condition still exists, adjust the front cross-camber by up to +1.0 degrees in the same manner as caster was adjusted in Step 3. Evaluate the vehicle for pull in both left and right sloping road crown/camber road surfaces and verify normal operation mentioned in step 1.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
8070032	Wheel Alignment Measurement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the

remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION