



Service Bulletin

File in Section: -

Bulletin No.: PI1347

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Lane Departure Warning Intermittently Defaults Back to Audible Sound Only, DTCs B172E, B172F Set

Models: 2014 Cadillac ELR


Condition/Concern

Some customers may comment on the lane departure warning intermittently defaults back to audible sound only. Upon further inspection technicians may find DTCs B172E 01 or 02, B172F 01 or 02 set.



3999915

Note: The haptic motor is on the outboard side of the driver seat as shown above.



3999932

This condition may be due to pressure while sitting in the seat, and the haptic motor wire harness pigtail getting chafed when it comes in contact with the sharp edge of the cushion linkage.

Recommendation/Instructions



3999833



3999847



3999855

Repair the chafed wiring and reposition the wire harness (2) towards the front of the seat suspension (1) using tie straps. Refer to Wiring Repairs in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5430902	Wire-to-Wire Repair	Use Published Labor Operation Time