



Countries:	RUSSIA, AUSTRALIA, CANADA, UNITED STATES, PUERTO RICO, NEW ZEALAND	Document ID:	IK1201040
Availability:	ISIS	Revision:	5
Major System:	ENGINES	Created:	12/2/2013
Current Language:	English	Last Modified:	3/4/2014
Other Languages:	NONE	Author:	Steven Bell
Viewed:	1083		

[Less Info](#)
☒ Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark  View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful  13	Not Helpful  1
--	---	--	---	--	---	--	---

Title: AFI Fuel Supply Line Rubbing SPN 3556 FMI 7 Codes After Dealer Service


Applies To: EPA 2010 IBB MF 11/13/15L

DESCRIPTION

If the fuel lines are not routed correctly the AFI Fuel Supply line can rub through from the fuel system return line and cause regen issues or an inability to perform regens. Due to the ECM sensing a pressure issue in the line it will stop sending fuel to the AFI from the DSI so you will not see a fuel leak in the area. What you will see is a regen issue and aftertreatment temperatures not reaching the correct temp and eventually the ecm will abort the OBFCT.

NOTE:


See how the fuel system return line is rubbing into the afi supply line.






Example of a bad OBFCT with a hole in the AFI Fuel Supply Line

Notice AFT Fuel Doser CTL actuated 3 times to purge the air then went to 0 and AFT Fuel Pressure 2 never climbed off 0 PSI. This is why you won't see any leaks as there is no fuel actually getting sent to pressurize the line.




RESOLUTION

Need to inspect and verify that the afi supply line is secured to the AFI bracket with the P-Clip and that the line separator clip is installed on the return and afi line. Also, be sure the DSI supply line is not rubbing anything. See pic below.



Example of a good OBFCT after the AFI Fuel Supply Line was repaired

Notice the AFT Fuel Doser CTL actuated and stayed active and AFT Fuel Pressure 2 is working properly now.



PARTS INFORMATION

Part #	Description	Qty.
3005935C2	TUBE ASSY HYDROCARBON INJ FUEL	1

Warranty Information

Warranty Claim Coding:

Group:	12000
Noun:	559

Standard Repair Time(s):

Step	Description	SRT Link	Hours
1	Aftertreatment Fuel Line, Replace	N12-7352U-21	2.0

OTHER RESOURCES

- [0000001741 - MaxxForce 11 and 13 Engine Diagnostic Manual](#)
- [0000001682 - MaxxForce 11 and 13 Engine Service Manual](#)

Viewed: 1082

Helpful: 13

Not Helpful: 1

No Feedback Found

Copyright © 2014 Navistar, Inc.