

Technical Information Service 74/14 ENU WE45 2

WE45 - Re-programming DME Control Unit (Workshop Campaign)

Important: CRITICAL WARNING - THIS CAMPAIGN INCLUDES STEPS WHERE SEVERAL CONTROL UNITS IN

THE VEHICLE WILL BE PROGRAMMED WITH THE PIWIS TESTER. IT IS CRITICAL THAT THE VEHICLE VOLTAGE BE BETWEEN 13.5 VOLTS AND 14.5 VOLTS DURING THIS PROGRAMMING. OTHERWISE, THE PROGRAMMING COULD FAIL RESULTING IN DAMAGED CONTROL UNITS. CONTROL UNITS DAMAGED BY INADEQUATE VOLTAGE WILL NOT BE COVERED UNDER WARRANTY. THE TECHNICIAN MUST VERIFY THE ACTUAL VEHICLE VOLTAGE IN THE INSTRUMENT CLUSTER OR IN THE PIWIS TESTER BEFORE STARTING THE CAMPAIGN AND ALSO DOCUMENT THE ACTUAL VOLTAGE ON THE REPAIR ORDER. IT IS ALSO ADVISABLE TO MONITOR THE VEHICLE VOLTAGE DURING THE PROGRAMMING VIA THE INSTRUMENT CLUSTER. PLEASE REFER TO EQUIPMENT INFORMATION EQ. 1105 FOR A LIST OF SUITABLE BATTERY CHARGERS/POWER SUPPLIES WHICH SHOULD BE USED TO MAINTAIN VEHICLE VOLTAGE.

Model Year: **As of 2010 up to 2014**

Vehicle Type: Panamera/Panamera 4/Panamera S/Panamera 4S/Panamera GTS

Panamera Turbo/Panamera Turbo S

Equipment: • Emissions concept LEV2 (I-no. 162)

Emissions concept ULEV2 (I-no. 164)

Concerns: DME control unit

Information: This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles. **Certain**

environmental conditions and the quality of fuel available in the market can cause combustion residue to build up on the throttle valve on the affected vehicles over the service life of the

vehicle.

This can impair the diagnostic function for the throttle valve and as a result, the Check Engine warning

light will be activated.

Action

Re-program DME control unit.

Required:



Information

In addition to the **DME control unit**, the **PDK control unit** is also re-programmed automatically. It takes **approx**. **12 minutes** in total to **program** the control units.

Affected Vehicles:

The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the vehicle. This campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper

repair. This campaign affects 21,879 vehicles in North America.



Information

Exceptions during vehicle assignment:

• In model year 2010 (A), only vehicles with the I-no. 750 are assigned to the campaign.



Information

If other programming campaigns that affect the **same control unit** and involve the **identical procedure** are open for a vehicle in addition to this campaign, the affected control unit must only be programmed **once** using the **current PIWIS Testert software**.

Only the latest campaign must be invoiced during warranty processing.

Other open programming campaigns that affect the same control unit and involve the identical procedure must therefore no longer be carried out.

Proceed as follows in this case:

- Mark the campaign as 'cannot be carried out' with the reason "Modification of the affected
 component" in PQIS. The "Warranty relevance" flag must be activated in order to be able to set a
 warranty claim and close the campaign.
- A warranty claim must be submitted for the campaign in which O TU is entered as the specified working time and no material items are specified.

Work

See Attachment "A".

Procedure:

Claim See Attachment "B".

Submission:

Attachment "A"



Fault entry in the fault memory and control unit programming aborted due to low voltage.

- Increased current draw during diagnosis or control unit programming can cause a drop in voltage, which
 can result in one or more fault entries and the abnormal termination of the programming process.
- ⇒ Before starting control unit programming, connect a battery charger or power supply, suitable for AGM type batteries, recommended current rating of 70A fixed voltage 13.5V to 14.5V.

NOTICE

Control unit programming will be aborted if the Internet connection is unstable.

 An unstable Internet connection can interrupt communication between PIWIS Tester II and the vehicle communication module (VCI). As a result, control unit programming may be aborted.

Technical Information	Service			
	74/14 ENU	WE45		

⇒ During control unit programming, always connect PIWIS Tester II to the vehicle communication module (VCI) via the USB cable.

NOTICE

Control unit programming will be aborted if the vehicle key is not recognized

- If the vehicle key is not recognized in vehicles with Porsche Entry & Drive, programming cannot be started or will be interrupted.
- ⇒ Switch on the ignition using the original vehicle key. To do this, replace the original vehicle key in the ignition lock with the plastic key fob if it was previously removed at the start of this procedure.

Tools: 9818 - PIWIS Tester II with PIWIS Tester software version 14.300 (or higher) installed.

• **Battery Charger/Power Supply** - Suitable for AGM Type batteries, recommended current rating of 70A fixed voltage 13.5V to 14.5V. Refer to Equipment Information EQ-1105.

Work NOTE: VEHICLE VOLTAGE MUST REMAIN BETWEEN 13.5 AND 14.5 VOLTS DURING THE ENTIRE WORK Procedure: PROCEDURE.

1 Carry out general preliminary work for control unit programming as described in ⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Preliminary work".

Carrying out control unit programming

Work NOTE: VEHICLE VOLTAGE MUST REMAIN BETWEEN 13.5 AND 14.5 VOLTS DURING THE ENTIRE WORK Procedure: PROCEDURE.

Re-program DME control unit.

The basic procedure for programming a control unit is described in the Workshop Manual · ⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Programming".

Specific information on control unit programming during this campaign:

Required PIWIS Tester software version:	14.300 (or higher)
Type of control unit programming:	Control unit programming using the 'Automatic programming' function for the DME control unit.
	DME control unit > ⇒ 'Programming' menu >> 'Automatic programming' function.

Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the DME control unit - as well as the PDK control unit - is re-programmed and then re-codedautomatically. Do not interrupt programming and coding.				
Programming time (approx.):	• 12 minutes				
Procedure in the event of error messages appearing during the programming sequence:	⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Troubleshooting".				
Procedure in the event of abnormal termination of control unit programming:	Repeat control unit programming by restarting programming.				

2 If previously disconnected, re-connect the electric plug connection for the fan blower.

Performing throttle valve adaptation

Work NOTE: VEHICLE VOLTAGE MUST REMAIN BETWEEN 13.5 AND 14.5 VOLTS DURING THE ENTIRE WORK Procedure: PROCEDURE.

- Select the 'DME' control unit in the control unit selection screen ('Overview' menu) and press
 •>>" to confirm your selection.
- Once the DME control unit has been found and is displayed in the overview, select the ⇒ 'Main-tenance/repairs' menu.
- Select menu item ⇒ 'Adaptations' and press
 >> " to confirm your selection ⇒ DME Adaptations.



DME - Adaptations

74/14 ENU

WE45

4 Comply with the displayed preconditions and press •>>" to confirm ⇒ Adaptation preconditions.



Adaptation preconditions

5 Select the ⇒ 'Throttle valve adaptation' function so that the corresponding text line turns blue and press • F8" to start the throttle valve adaptation.



Throttle valve adaptation


- 6 Follow the instructions on the PIWIS Tester while throttle valve adaptation is being performed.
 Once throttle valve adaptation is complete, a tick will appear in the "Value" field on the PIWIS Tester display.
 - If throttle valve adaptation is **not** completed successfully, adaptation must be **repeated**.
- 7 Press F8" ("Stop") to end throttle valve adaptation.
- 8 Press •<<" to return to the start page of the ⇒ 'Maintenance/repairs' menu.
- 9 Select the ⇒ **'Overview'** menu and press •<<" to return to the control unit selection screen.

Reading out and erasing fault memories

Work NOTE: VEHICLE VOLTAGE MUST REMAIN BETWEEN 13.5 AND 14.5 VOLTS DURING THE ENTIRE WORK Procedure: PROCEDURE.

- 1 In the control unit selection screen (⇒ 'Overview' menu), press •F7" to call up the Additional menu.
- 2 Select the function "Read all fault memories and erase if required" and press ◆>>" to confirm ⇒ Erasing fault memories.

The fault memories of the control units are read out.



Erasing fault memories

- 3 Once you have read out the fault memories, delete the fault memory entries by pressing F8".
- 4 Press F12" ("Yes") in response to the question as to whether you really want to erase all fault memory entries.

The faults stored in the fault memories of the various control units are deleted.



Information

If the fault memories of individual control units (e.g. fault memories of the control units DME, Adaptive Cruise Control (ACC), etc.) cannot be erased, proceed as follows:

- Switch off ignition.
- Disconnect the PIWIS Tester diagnostic connector from the diagnostic socket.
- Lock the vehicle using the driver's key.
- Wait approx. 1 minute before unlocking the vehicle again.
- Plug the PIWIS Tester diagnostic connector into the diagnostic socket again and restore communication with the vehicle.
- Read out the fault memories of these control units again and erase the fault memories separately.

If control units are found to have faults which cannot be erased and are not caused by control unit programming, these faults must be found and corrected. This work **cannot** be invoiced under the workshop campaign number.

74/14 ENU WE45

5 Once you have erased the fault memories, select the ⇒ 'Overview' menu and press •<<" to return to the control unit selection screen ⇒ Control unit selection.



Control unit selection

Subsequent work



Exhaust gases

- Risk of Carbon Monoxide (CO) Poisoning
- ⇒ Before starting the engine, position an exhaust extraction system behind the vehicle's exhaust pipes and switch it on.



Information

If it is necessary to achieve the ready status after the control units have been programmed, the short tests required for this must be carried out before engine torque loss adaptation is performed (see next step). If in doubt, please contact your importer.

The short tests required to achieve the ready status can be called up using the PIWIS Tester in the control unit \Rightarrow '**DME**' in the \Rightarrow '**Maintenance/repairs**' menu under the "Short tests" function.

- The preconditions specified in the PIWIS Tester must be met in order to perform the short tests.
- An engine cold start is required in order to achieve the ready status for the valve lift.
- Do not move the vehicle and bring the engine to the required temperature at idle speed.
- Perform the short tests in sequence.
- Some ready states can only be achieved by means of a test drive under specific driving conditions. If in doubt, contact your importer.
- If a test drive is carried out, this must be done after engine torque loss adaptation.

Work Procedure:

NOTE: VEHICLE VOLTAGE MUST REMAIN BETWEEN 13.5 AND 14.5 VOLTS DURING THE ENTIRE WORK PROCEDURE.

1 Perform engine torque loss adaptation.

To obtain the engine temperature required for engine torque loss adaptation (176° F/80° C), leave the engine running in selector-lever position "P" until the required temperature is reached.

Conditions/procedure for engine torque loss adaptation:

- Engine temperature is at least 176° F (80° C) (the engine temperature can be read out in the "Actual values" menu using the PIWIS Tester).
- Position steering wheel straight ahead.
- PDK selector lever in position P.
- Leave engine running at idle speed for 3 minutes with air conditioning switched off.
- Then leave engine running at idle speed for 3 minutes with air conditioning switched on (normal load).
- 2 Switch off ignition.
- 3 Disconnect the PIWIS Tester from the vehicle.
- 4 Switch off and disconnect the battery charger.
- 5 On vehicles with Porsche Entry & Drive, replace the original driver's key in the ignition lock with the control panel again.
- 6 Enter the workshop campaign in the Warranty and Maintenance booklet.

Attachment "B"



Information

The specified working time was determined specifically for carrying out this campaign and includes all required preliminary and subsequent work.

The working time may differ from the working times published in the Labor Operation List in PIWIS.

Claim Submission - Workshop Campaign WE45

Warranty claims should be submitted via WWS/PQIS.

Open campaigns may be checked by using either the PIWIS Vehicle Information system or through PQIS Job Creation.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/PQIS. If necessary, the required part numbers will need to be manually entered into warranty system by the dealer administrator.

Technical Information

Service

74/14 ENU WE45

2

Labor time: 57 TU

Scope:

Working time:

Re-programming DME and PDK control unit

Includes: Connecting and disconnecting battery charger

Connecting and disconnecting PIWIS Tester

Performing throttle valve adaptation Performing engine torque loss adaptation Reading out and erasing fault memories

⇒ Damage code WE45 066 000 1

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

Dealership	Service Manager	 Shop Foreman	 Service Technician	 	
Distribution	A + M	\\/	Comito Tookaisiaa		
Routing	Asst. Manager	 Warranty Admin.	 Service Technician	 	

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, 918 Spyder®, Tiptronic®, VarioCam®, PCM®, PDM®, 911®, RS®, 48®, FOUR, UNCOMPROMISED®, and the model numbers and the distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and other elements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal authorized Porsche dealer use only and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.