

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2011-2012	All	All	A3_BC000001	A3_CC025567
Passat	2014	All	All	A3_EC050001	A3_EC103000

### **Condition**

40 14 03 June 24, 2014 2028353 Supersedes V401402 dated May 21, 2014 to extend the 2014 Passat VIN range.

### **Front Suspension Creaking Noise**

Front suspension creaking noise during suspension cycles (going over speed bumps or entering on an inclined surface).

# **Technical Background**



Model Year 2013 Passat DOES NOT apply to this technical bulletin content.

Coil Spring is not formed correctly and rubs against the perch of the strut.

## **Production Solution**

Improved parts installed in production since CW 18/14, VIN: A3\_EC103000.

# (W)

# **Technical Bulletin**

### **Service**



Figure 1

• Verify if a car with the creaking noise has the contact mark (on one side or on both sides) as shown in figure 1.



Only proceed with this TB if this is the case!

- Remove affected suspension strut and disassemble, see Repair Group 40 in Elsa.
- Apply touch up paint to the contact area of the strut perch and allow required drying time.



Use Rustoleum Cold Galvanizing Compound # V2185838 (or similar obtained locally), 2 coats. Cover with Rustoleum Flat Black Spray Paint # V2178838 (or similar obtained locally), 1 coat.

- Install new spring on suspension strut (per vehicle PR-codes).
- Install suspension strut, see Repair Group 40 in Elsa.



Replace all fasteners as required in repair procedure.

## **Warranty**

variancy	vvarianty							
To determine if t		dure is co	vered under	Warranty, always	refer to	the Warranty	Policies and	
Model(s)	Year(s)		Eng. Code(s)	Trans. Code(s)	VIN	Range From	VIN Range To	
Passat	ssat 2011-2012		All	All	A3_BC000001		A3_CC025567	
Passat 2014		All	All	A3_EC050001		A3_EC103000		
SAGA Coding								
Claim Type:	Claim Type:  Use applicable Claim Type 1)							
Service Number:			mage Code	HST			ocation (Depends on ervice No.)	
4075		O	0020			Use applicable when indicated in ElsaWeb (L/R)		
Parts Manufacturer			Passat		YXS <sup>2)</sup>			
Repair One Side								
Labor Operation <sup>3)</sup> : Remove and Install Coil Spring				40751950 = 30 TU				
Labor Operation <sup>3)</sup> : Remove and Install Suspension Strut			40851900 = 130 TU					
Repair Both Sides								
Labor Operation <sup>3)</sup> : Remove and Install Coil Spring			40752050 = 40 TU					
Labor Operation <sup>3)</sup> : Remove and Install Suspension Strut			40852000 = 190 TU					
Causal Part: Spring			3C0411105B/C					
Outside Material: Rustoleum Cold Galvanizing Compound			V2185838	\$0.25				
Outside Material: Rustoleum Flat Part No: # \Black Spray Paint			V2178838	\$0.15				



Diagnostic Time <sup>4)</sup>			
GFF Time expenditure	01500000 = 00 TU max.	NO	
Road Test	01210002 = 10 TU	YES	
	01210004 = 10 TU		
Technical Diagnosis	01320000 = 00 TU max.	NO	

Claim Comment: Input "As per Technical Bulletin 2028353" in comment section of Warranty Claim.

# **Required Parts and Tools**

Part Description	Part No:	Quantity	
Spring	3C0411105B/C	1 per side	
Nut	N 10106402	1 per side	
Nut	N 91021601	1 per side	
Nut	N 10332002	3 per side	
Nut	N 0150816	1 per side	
Bolt	WHT005437	1 per side	
Rustoleum Cold Galvanizing Compound	Part No: # V2185838	\$10.00 per 20 oz. can, with 1 can repairing 40 cars	
Rustoleum Flat Black Spray Paint	Part No: # V2178838	\$7.20 per 15 oz. can, with 1 can repairing 50 cars	

<sup>&</sup>lt;sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

<sup>&</sup>lt;sup>2)</sup> Code per warranty vendor code policy.

<sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.

<sup>4)</sup> Documentation required per Warranty Policy Procedures Manual.



Tool Description	Tool No:
Torque Wrench	VAG 1332
Spreader	3424
Wheel Hub Support	T10149
Engine/Transmission Jack	VAG 1383 A
Spring Compressor	VAG 1752/1
Spring Holder	VAG 1752/4
Holding Fixture for Suspension Struts	VAG 1752/20
Shock Absorber Set	T10001

### **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.