

Technical Service Bulletin



46 Rattling noises from front axle on uneven roads (brake disc)

46 14 65 2035113/3 January 3, 2014. Supersedes Technical Service Bulletin Group 46 number 13-60 dated October 16, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2011 - 2013	All	Not Applicable
SQ5	2013 - 2014	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header data (Added SQ5) Revised <i>Warranty</i> (Added SQ5)
2	10/16/2013	Revised <i>Attachments</i> (Changed video file formats)
1	08/26/2013	Initial publication

Customer may report rattling noises from front axle on uneven roads.

Technical Background

There are conflicting tolerances in the alignment of pin and hole on the front brake discs.

Production Solution

Not applicable.

Technical Service Bulletin



Service

1. Verify that the noise is coming from the front of the vehicle.
2. Remove the front wheels and front brake discs.



Tip: Place the brake disc on the brake disc hub (wheel contact surface) so that the friction surface is not damaged during testing.

3. Check the brake discs according to the attached videos. Multiple versions of each video are attached to accommodate various video players and internet browsers.
 - If the brake discs sound like the sound in video 1, the brakes can stay on the vehicle.
 - If the brake discs sound like the sound in video 2, the brake disc pins are loose and are the cause of the rattling noise. Replace both front brake discs.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4650		
Damage Code:	0020		
Labor Operations:	2 front wheels remove + reinstall	4405 2000	20 TU
	2 front brake discs remove + reinstall	4650 2050 (A8) 4650 2050 (SQ5)	50 TU (A8) 40 TU (SQ5)
	Check 2 front brake discs	4650 0299	5 TU
Diagnostic Time:	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure Only applicable if the front brake discs were replaced.	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2035113/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB (2035113) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.