# Audi

## Technical Service Bulletin

#### 94 Xenon headlight flickers or is inoperative on one side (DTC 00978 or 00979)

94 14 31 2021751/4 January 16, 2014. Supersedes Technical Service Bulletin Group 94 number 10-19 dated June 7, 2010 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4	2009	N000001 - N050000 A000001 - A179000		
A5	2008	All	Xenon headlights	
A5	2009	000001 - 034000		
Q5	2009	000001 - 003400		

### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
4	-	Revised header data (Added DTCs)  Revised Service (Clarified instructions)		
		Revised Warranty (Corrected labor operations)		
3	6/7/2010	Revised Warranty		
2	4/29/2010	Revised <i>Service</i> (Clarification of procedure and bulb date code decoder)  Revised <i>Warranty</i>		
1	10/6/2009	Original publication		

- The xenon headlight on one side of the vehicle flickers or is inoperative. The condition may be intermittent or permanent.
- One of the following DTCs is stored in the electronic central electronics control module, J519, (address word 09) for the affected headlight:
  - DTC 00978 (Left Low Beam Headlight -M29- Electrical fault in circuit).
  - DTC 00979 (Right Low Beam Headlight -M31- Electrical fault in circuit).
- Only xenon bulbs manufactured by Philips are affected.

# Audi

## Technical Service Bulletin

## **Technical Background**

The xenon bulb may have an internal leak at the crimp of the electrodes, and xenon gas can be released (Figure 1).

Without an adequate amount of xenon gas, the bulb cannot establish a stable light arc. The xenon igniter control unit (ballast) repeatedly tries to establish an arc, which may cause a flickering of the headlight.




Figure 1. The location of the xenon bulb leak.

### **Production Solution**

Improved xenon bulbs in production.

### **Service**

#### If the condition occurs permanently:

- 1. Swap the bulbs between the left and right headlights.
  - If the condition does not follow the bulb:
     Check the power supply and control unit of the headlight assembly according to Guided Fault Finding.
  - If the condition does follow the bulb:
     Proceed to step 1 under If the condition occurs intermittently, below.

# Audi

## Technical Service Bulletin

#### If the condition occurs intermittently:

 Locate the 4-digit alphanumeric production date code on the label of each of the xenon bulbs (Figure 1)



Figure 1. Location of the 4-digit alphanumeric production date code.

- 2. Determine the production of the xenon bulbs by using the *Production Date Decoder* table below.
  - If the bulbs were produced before June 1, 2008:
     Replace both bulbs, even without a customer complaint. The bulbs will be covered under the New Vehicle Limited Warranty (NVLW) extension.
  - If the bulbs were produced on or after June 1, 2008:
     Replace only the failing bulb. The bulb will be covered under the New Vehicle Limited Warranty (NVLW) extension.



# Technical Service Bulletin

Production Date Decoder (read code from left to right)

If the first character is a letter:			If the first character is a number:		
First character:	A = January	G = July	First character:	0 = 2010	
(Indicates month)	B = February	H = August	(Indicates year)	1 = 2011	
	C = March	J = September		2 = 2012	
	D = April	K = October		3 = 2013	
	E = May	L = November			
	F = June	M = December			
Second	6 = 2006		Second character:	A = January	G = July
character:	7 = 2007		(Indicates month)	B = February	H = August
(Indicates year)	8 = 2008			C = March	J = September
	9 = 2009			D = April	K = October
				E = May	L = November
				F = June	M = December
Third and fourth	01 = 1st	17 = 17th	Third and fourth	01 = 1st	17 = 17th
characters:	02 = 2nd	18 = 18th	characters:	02 = 2nd	18 = 18th
(Indicate day)	03 = 3rd	19 = 19th	(Indicate day)	03 = 3rd	19 = 19th
	04 = 4th	20 = 20th		04 = 4th	20 = 20th
	05 = 5th	21 = 21st		05 = 5th	21 = 21st
	06 = 6th	22 = 22nd		06 = 6th	22 = 22nd
	07 = 7th	23 = 23rd		07 = 7th	23 = 23rd
	08 = 8th	24 = 24th		08 = 8th	24 = 24th
	09 = 9th	25 = 25th		09 = 9th	25 = 25th
	10 = 10th	26 = 26th		10 = 10th	26 = 26th
	11 = 11th	27 = 27th		11 = 11th	27 = 27th
	12 = 12th	28 = 28th		12 = 12th	28 = 28th
	13 = 13th	29 = 29th		13 = 13th	29 = 29th
	14 = 14th	30 = 30th		14 = 14th	30 = 30th
	15 = 15th	31 = 31st		15 = 15th	31 = 31st
	16 = 16th			16 = 16th	



# Technical Service Bulletin

## **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9459				
Damage Code:	0040				
Labor Operations:	For A4 and A5 - If one bulb was replaced:				
	1 Headlight assembly remove+reinstall	9415 1901	50 TU		
	1 Gas discharge bulb remove+reinstall	9459 1950	10 TU		
	2 Headlight assembly adjust	9415 1600	20 TU		
	For A4 and A5 - If both bulbs were replaced:				
	2 Headlight assembly remove+reinstall	9415 2001	70 TU		
	2 Gas discharge bulb remove+reinstall	9459 2050	20 TU		
	2 Headlight assembly adjust	9415 1600	20 TU		
For A4 and A5 - If bulbs were tested due to perman			anent failure:		
	2 Gas discharge bulb remove+reinstall	9459 2050	20 TU		
	Test/swap 2 gas discharge bulbs	9459 3299	20 TU		
	2 Headlight assembly adjust	9415 1600	20 TU		
	For Q5 - If one bulb was replaced (left side):				
	1 Gas discharge bulb remove+reinstall	9459 1900	50 TU		
	2 Headlight assembly adjust	9415 1600	20 TU		
	For Q5 - If one bulb was replaced (right side):				
	1 Gas discharge bulb remove+reinstall	9459 1901	90 TU		
	2 Headlight assembly adjust	9415 1600	20 TU		



# Technical Service Bulletin

	For Q5 - If both bulbs were replaced:			
	2 Gas discharge bulb remove+reinstall	9459 2000	110 TU	
	2 Headlight assembly adjust	9415 1600	20 TU	
	For Q5 - If bulbs were tested due to permanent failure:			
	2 Gas discharge bulb remove+reinstall	9459 2000	110 TU	
	Test/swap 2 gas discharge bulbs	9459 3299	20 TU	
	2 Headlight assembly adjust	9415 1600	20 TU	
Diagnostic Time: (All vehicles)	GFF – Checking and clearing fault codes and basic settings	0150 0000	Time stated on diagnostic protocol (Max 40 TU)	
	Road test prior to service procedure	No allowance	0 TU	
	Road test after service procedure	No allowance	0 TU	
Technical diagnosis at dealer's discretion  (Refer to Section 2.2.1.2 and Audi Warranty Online for			vance details)	
Claim Comment:	As per TSB #2021751/4			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Additional Information**

All parts and service references provided in this TSB (2021751) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.