

Technical Service Bulletin



37 Harsh downshifts when braking or harsh 1-2 upshift under acceleration

37 14 33 2029305/10 July 1, 2014. Supersedes Technical Service Bulletin Group 37 number 13-96 dated March 4, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, allroad	2013	A000001 - A155856 N000001 - N028462	8-speed OBK
A5	2013	000001 - 037910	8-speed OBK
A5 Cabriolet	2013	000001 - 007044	8-speed OBK
Q5	2013	000001 - 032893	8-speed OBK
A6, A7	2013	000001 - 075006	8-speed OBK
A8	2012	All	8-speed OBK
A8	2013	000001 - 012006	8-speed OBK

Condition

REVISION HISTORY		
Revision	Date	Purpose
10	-	Revised <i>Service</i> (SVM code changed; increased software levels)
9	3/4/2013	Republished to correct Elsa display error
8	2/6/2013	Revised header data (VIN range missing)
7	1/31/2013	Revised header data (Removed 2011-12 vehicles)
6	1/8/2013	Revised header data (VIN range increased)
5	12/19/2012	Revised <i>Service</i> (Increased software levels) Revised header data (Further models)
4	11/28/2012	Revised header data (VIN range increased)
3	11/8/2012	Revised <i>Service</i> (new SVM code)
2	6/28/2012	Revised <i>Service</i> (Added Step 4)
1	4/23/2012	Original publication

Customer may report harsh downshifts while braking or harsh 1-2 upshift under acceleration.

Technical Service Bulletin



Technical Background

Further transmission control module (TCM), J217 (address word 02), software calibration to improve shift concerns.

Production Solution

New software in the TCM addresses the condition.

Service

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the TCM using the SVM action code as listed in the table below, if necessary.

Model	Engine and Transmission	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Action Code
A4, A5, A5 cabriolet allroad	2.0 L with 0BK 8 speed transmission	8K0927158T	All	8K0927158T	1005	02A072
allroad	2.0 L with 0BK 8 speed transmission	8K1927158	All	8K1927158	1005	
Q5	2.0 L with 0BK 8 speed transmission	8R1927158C	All	8R1927158C	1006	
Q5	3.0 L with 0BK 8 speed transmission	8R0927158AM	All	8R0927158AM	1003	
A6/A7	2.0 L with 0BK 8 speed transmission	4G0927158AD	All	4G0927158AD	1004	
A6/A7	3.0 L with 0BK 8 speed transmission	4G1927158A	All	4G1927158A	1006	
A8	3.0 L with 0BK 8 speed transmission	4H1927158AR	All	4H1927158AR	1007	

Technical Service Bulletin



4. Clear adaptations and perform standstill adaptation for 2013 model year.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	3730		
Damage Code:	0039		
Labor Operations:	Update software of TCM	3735 2599	50 TU
	Perform standstill adaptation	3735 5799	60 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2029305/10		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732 00 *Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2029305) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.