ACURA Service Bulletin

14-001

Applies To: 2013 RDX AWD – ALL

2014 RDX AWD - From VIN 5J8TB4...EL000001 thru 5J8TB4...EL019936

Vibration at Highway Speeds During VCM Operation

(Supersedes 14-001, dated January 15, 2014, to revise the information marked by the black bars)

REVISION SUMMARY

Under Applies To, a VIN range has been added to the 2014 model.

SYMPTOM

In cold ambient conditions (below-freezing temps) a vibration is felt in the front seats and floor at highway speeds during light throttle operation.

POSSIBLE CAUSE

The rubber in the companion flanges absorbs vibration poorly in cold temperatures.

CORRECTIVE ACTION

Replace the propeller shaft.

PARTS INFORMATION

Propeller Shaft Assembly: P/N 40100-TX4-A02

Bolt (12 point, 8 mm x 21 mm) (eight required): P/N 90113-S10-000

Flange Bolt (10x29) (two required): P/N 90382-SH9-003

WARRANTY CLAIM INFORMATION

The normal warranty applies. Operation Number: 2191W4 Flat Bate Time: 1.0 hour

riat riato rimo.	1.0 11001
Failed Part:	P/N 40100-TX4-A01
Defect Code:	01601
Symptom Code:	04501
Skill Level:	Repair Technician
Template ID:	14-001N

DIAGNOSIS

NOTE: Make sure the vehicle is cold soaked (let it sit overnight) before doing this test drive.

1. Test-drive the vehicle, paying close attention to the speed ranges when the vibration occurs and where it occurs.

NOTE: Make notes of where the vibrations are felt, (floor, seat, pedal, steering wheel, etc.) and the timing of when the vibration occurs relative to road/ vehicle conditions (uphill, downhill, flat, VCM mode, etc.)

2. Pull over safely to the side of the road, and disconnect the rear rocker arm oil pressure switch connector, disabling the VCM operation.



REAR ROCKER ARM OIL PRESSURE SWITCH CONNECTOR

- 3. Drive the vehicle under the same conditions that caused vibration to occur.
 - If the vibration still occurs, this bulletin does not apply. Continue with normal troubleshooting.
 - If the vibration is gone, go to REPAIR PROCEDURE.

 ${\ensuremath{\textcircled{}^\circ}}$ 2014 American Honda Motor Co., Inc. – All Rights Reserved

BTB 50754-51011 REV 1 (1402)

1 of 4

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.



February 18, 2014

REPAIR PROCEDURE

1. Remove the No. 1 propeller shaft protector.



No. 1 PROPELLER SHAFT PROTECTOR

2. Remove the No. 2 propeller shaft protector.



No. 2 PROPELLER SHAFT PROTECTOR

3. Remove the No. 1 propeller shaft flange bolts.



TRANSFER COMPANION FLANGE

4. Remove the center support bearing mounting bolts.



REAR DIFFERENTIAL COMPANION FLANGE

6. With the help of an assistant, install the new No. 1 propeller shaft to the transfer companion flange and loosely install the new flange bolts.



TRANSFER COMPANION FLANGE

 With the continued help of an assistant, install the new No. 2 propeller shaft onto the rear differential companion flange and torque the No. 2 flange bolts to 32 N•m (24 lb-ft).



REAR DIFFERENTIAL COMPANION FLANGE

 Install the new center support bearing mounting bolts and torque them to 39 N•m (29 lb-ft). Then torque the No. 1 flange bolts to 32 N•m (24 lb-ft).



NEW CENTER SUPPORT BEARING MOUNTING BOLTS 39 N·m (29 lb-ft)

 Install the No. 1 and No. 2 propeller shaft protectors, then torque the bolts to 22 N•m (16 lb-ft).



10. Lower the vehicle to the ground.

- 11. Test drive the vehicle at 55 mph, and check for noise or vibration.
 - If there is no vibration, go to step 12.
 - If there is a vibration, make a reference mark across the No. 2 propeller shaft and the rear differential companion flange, then rotate the propeller shaft 180 degrees from that mark, and recheck.

NOTE: The rear rocker oil pressure switch coupler should still be disconnected during this test drive.



- 12. Reconnect the rear rocker oil pressure switch coupler.
- 13. Clear any DTCs with the HDS.