

Service

Category Vehicle Interior

Section Heating/Air Conditioning Market USA



### **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2014	Tacoma	

#### Introduction

Some 2014 model year Tacoma vehicles may exhibit a condition where the blower motor only operates on high speed and all other blower speeds are inoperative. The blower motor resistor connector terminals have been updated to address this condition.

### **Production Change Information**

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	PLANT	DRIVETRAIN	WHEEL BASE	ENGINE	CAB TYPE	PRODUCTION CHANGE EFFECTIVE VIN
			Short	2TR-FE	Regular	5TFNX4CN#EX037496
		·			Access	5TFTX4CN#EX041915
				1GR-FE	Double	5TFJX4CN#EX041924
					A 00000	5TFTU4CN#EX001877
		2WD	Long	2TR-FE	Access	5TFTX4GN#EX031710
		MTX 4WD		ZIK-FE	Double	5TFJX4GN#EX031709
Tacoma	TNANAT∨			1GR-FE	Access	5TFTU4GN#EX057062
Tacoma	I IVIIVI I A				Double	5TFJU4GN#EX057039
			S-Long		Double	5TFKU4HN#EX005069
			Short	2TR-FE	Regular	5TFPX4EN#EX021128
				ZIK-FE	Access	5TFUX4EN#EX026805
			Long		Access	5TFUU4EN#EX095916
				1GR-FE	Double	5TFLU4EN#EX095872
			S-Long		Double	5TFMU4FN#EX023480

T-SB-0025-14 April 15, 2014 Page 2 of 12

## **Blower Motor Only Operates on High Speed**

### **Production Change Information (Continued)**

MODEL	PLANT	DRIVETRAIN	WHEEL BASE	ENGINE	CAB TYPE	PRODUCTION CHANGE EFFECTIVE VIN
	TMMBC	OWD	Long	1GR-FE	R-FE Double	3TMJU4GN#EM165793
Tagama		2WD	S-Long			3TMKU4HN#EM040502
Tacoma		TIVIIVIDO	4WD	Long	IGK-FE	Double
			S-Long			3TMMU4FN#EM067425

#### **Parts Information**

**TOYOTA** 

PART NUMBER	PART NAME	QTY
82141-04M40	Wire Pigtail	1
82999-12030	Terminal Joint Repair	4

### **Required Tools & Equipment**

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Wire Crimper (Non Insulated)*	<u>09042-2C100</u>	1

<sup>\*</sup> Essential SST.

### **NOTE**

Additional SSTs may be ordered by calling 1-800-933-8335.

MATERIAL	QTY
Electrical Tape	1



### **Warranty Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EL1407	Wire, Instrument Panel	1.1	82141-####*	72	41

<sup>\*</sup> Select the OFP by confirming the vehicle components/options using the tables below.

### **APPLICABLE WARRANTY**

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

	2TR-FE ENGINE						
TRANS	DRIVE- TRAIN	DOOR SPEAKERS	ROOF SPEAKERS	JBL AUDIO	DOOR LOCK	OPTION	OFP
	OMD	Х	_	-	-	_	82141-04K71
NA/T	2WD	_	Х	_	Х	_	82141-04K81
M/T	414/D	Х	_	_	_	_	82141-04K91
	4WD	_	Х	_	Х	_	82141-04L01
		Х	_	_	_	_	82141-04L11
		Х	_	_	Х	Double Cab	82141-04L21
		Х	_	_	Х	110V Outlet	82141-04L31
	2WD	_	Χ	_	Х	Access Cab	82141-04L41
A/T		_	X	-	Х	Convenience Package	82141-04L51
		_	Χ	_	Х	110V Outlet	82141-04L61
	4WD	Х	-	_	_	_	82141-04L71
		_	Х	_	Х	_	82141-04L81
		_	Х	_	Х	Convenience Package	82141-04L91



### **Warranty Information (Continued)**

			1GI	R-FE ENGINE			
TRANS	DRIVE- TRAIN	DOOR SPEAKERS	ROOF SPEAKERS	JBL AUDIO	DOOR LOCK	OPTION	OFP
	2WD	_	Х	-	Х	_	82141-04M51
		-	Χ	-	Х	_	82141-04M61
M/T	4WD	_	Х	-	Х	Hydraulic Booster	82141-04M71
	4VVD	Х	_	-	Х	_	82141-04M81
		Х	-	_	Х	Hydraulic Booster	82141-04M91
		_	Х	_	Х	_	82141-04N01
		Х	_	_	Х	Double Cab	82141-04N11
	2WD	Х	_	_	Х	TRD Package	82141-04N21
		Х	_	-	Х	Seat Heater	82141-04N31
		_	_	Х	Х	Limited	82141-04N41
		_	_	Х	Х	Seat Heater	82141-04N51
		_	Х	_	Х	_	82141-04N61
A/T		_	Х	-	Х	Hydraulic Booster	82141-04N71
		Х	I	_	Х	Double Cab	82141-04N81
		Х	ı	_	Х	Seat Heater	82141-04N91
	4WD	Х	-	_	Х	Hydraulic Booster	82141-04P01
		_	1	Х	Х	Limited	82141-04P11
		_	1	Х	Х	Seat Heater	82141-04P21
		_	-	Х	Х	Hydraulic Booster	82141-04P31

### **TOYOTA**

## **Blower Motor Only Operates on High Speed**

### **Repair Procedure**

1. Verify the blower motor only operates on high speed.

#### **NOTE**

If the blower motor operates on any speed other than high, this bulletin does NOT apply.

- 2. Disconnect the negative (-) battery cable.
- 3. Disconnect, remove, and inspect the blower motor resistor fuse.

Figure 1.





Figure 2. Fuse Intact




**TOYOTA** T-SB-0025-14 April 15, 2014 Page 6 of 12

### **Blower Motor Only Operates on High Speed**

### **Repair Procedure (Continued)**

Figure 3. Fuse Open



Inspect the fuse. Is the fuse intact?

- YES Continue to step 4.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

### **NOTE**

Steps 4 – 8 will need to be repeated for each of the 4 wires on the new connector pigtail.

4. Install the blower motor resistor and connect the new connector.

Torque: 2.0 N\*m (20 kgf\*cm, 18 in\*lbf)

#### **Repair Procedure (Continued)**

5. Cut the old connector from the harness using the new wire lead as a guide for proper length.

#### **NOTICE**

If the length of wire removed is NOT approximately the same length as the new piece, the following problems may develop:

- Too short tension on the terminal, splice, or the connector, causing an open circuit.
- Too long excessive wire near the connector, may get pinched or abraded, causing a short circuit.


6. Strip insulation from wire on the harness and replacement terminal lead.

Start stripping at least 8 mm (0.31 in.) to 11 mm (0.43 in.) away from the end of the existing harness at vehicle side and also from the end of the repair wire.

#### **NOTICE**


Make sure NOT to damage the wire when stripping the wire harness lead. After finishing the operation, visually inspect the wire. If there is any damage, perform the operation again.

Figure 4.



1	Existing Terminal
2	Cut
3	New Terminal with Lead


Figure 5.



1	Stripped Insulation Length (Approximately 8 – 11 mm)
2	Existing Harness
3	Supplied Lead with New Terminal

### **Repair Procedure (Continued)**

Figure 6.



7. Use the sleeve (P/N 82999-12030) to join the connector pigtail to the wire harness.

### **NOTE**


Part Number 82999-12030 is designed to fit with an outside diameter of 3.0 – 5.0 mm.



### **Repair Procedure (Continued)**

8. Crimp the replacement terminal lead to the harness lead.

Figure 7.



1	Good Example
2	Bad Example
3	2 Stripped Wires
4	Sleeve (Blue)


5	Pressure-Contact Section
6	Wire in Short Position
7	Wire Bend

- A. Overlap the 2 stripped wire ends inside the sleeve as shown.
- B. Place the sleeve into the 8 mm crimp die of the Wire Crimper (Non Insulated).

SST: 09042-2C100

#### **NOTE**

The Wire Crimper tool handles must be fully depressed for it to release. Verify alignment is proper prior to applying pressure to crimper handles.



C. With the center of the sleeve correctly placed between the crimping jaws, squeeze the crimping tool until this sleeve has been fully crimped.

#### **HINT**

Check to see that the sleeve and wires are still in the correct position before closing the crimping tool ends with steady pressure.

### **Repair Procedure (Continued)**


**TOYOTA** 

D. Pull the joined wires to either end. Make sure that they are joined firmly by the sleeve.

#### **NOTICE**

If the joined wires come loose, the splice is defective. Replace the sleeve and repeat the procedure.

Figure 9.



E. Apply additional crimps slightly beyond the crimp in the center. The end result should look similar to Figure 10.

Figure 10.



9. Protect joined section by wrapping electrical tape around the joints to protect them from moisture.

### **HINT**


- Before starting the operation, thoroughly wipe dirt and grease off the sections to be joined.
- · Do NOT let oil and dust, etc. get on the tape surface.

### **Repair Procedure (Continued)**

**TOYOTA** 

A. Stretch the electrical tape until its width is reduced by half.


Figure 11.



1	10 mm (0.39 in.)
2	3 or More Times

B. Starting approximately 10 mm (0.39 in.) from the end of the sleeve, wrap the electrical tape around the sleeve 3 or more times while stretching the tape.

Figure 12.




1	3 or More Times
2	10 mm (0.39 in.)



### **Repair Procedure (Continued)**

C. When wrapping the sleeve with electrical tape, overlap each wrap half the width of the tape.


Figure 13.



**Tape Overlapping** 

D. Firmly wrap the tape 2 times or more about 10 mm (0.39 in.) from the other end of the sleeve, then wrap the tape back towards the start again and firmly finish winding the tape around the center of the sleeve.

Figure 14.



1	10 mm (0.39 in.)
2	2 or More Times

- 10. Connect the negative (–) battery cable.
- 11. Verify the blower motor operates on all speeds.