



Service Bulletin

File in Section: 06 - Engine

Bulletin No.: 14-06-04-004A

Date: April, 2014

INFORMATION

Subject: Various Engine Noises During Cold Start and Warm Engine Operation

Models: 2014 Chevrolet Corvette
2014-2015 Chevrolet Silverado 1500
2015 Chevrolet Suburban, Tahoe
2014-2015 GMC Sierra 1500, Denali Models
2015 GMC Yukon, Yukon XL
Equipped with 4.3L – RPO LV3, 5.3L – RPO L83, 6.2L – RPO L86 or 6.2L – RPO LT1

This Bulletin has been revised to remove the Split Pulse Injection information section and add the Model Year 2014 Corvette. Please discard Corporate Bulletin Number 14-06-04-004.

Information For Why New Engine Technologies Are Generating Noises

The latest generation of full size trucks and utilities incorporate a new generation of technologies not previously seen in full size truck and utility applications. As a result these engines generate noises during cold start and during warm operation that owners of previous generation multipoint fuel injection (MFI) vehicles may not be familiar with.

Direct Injection (DI) / High Pressure Fuel Pump / Fuel Injectors

The new Small Block Generation 5 engine family incorporates a new fuel system technology known as Direct Injection (DI). With DI, fuel is injected directly into the cylinder using a high pressure fuel system. DI provides many benefits in improving engine efficiency. In particular, DI improves power, torque, and most importantly fuel efficiency. This technology is included as standard equipment on all Generation 5 engines in the Small Block engine family which are the: 4.3L V6, 5.3L V8, and 6.2L V8.

The high pressure fuel system does have unique operating characteristics, in particular the noise emanating from the high pressure fuel pump can result

in a subtle ticking noise that is apparent when the vehicle is idling. The sound is more evident when outside around the vehicle, when the hood is open or the vehicle is operated in a drive-through. The sound may be more noticeable during a cold start, but lessens once the engine is warm. A slightly higher pitched clicking sound is the fuel injectors pulsing **ON** and **OFF** under the high fuel pressures. These sounds are a normal characteristics of the DI high pressure fuel system.

Another operating characteristic is a slightly longer crank time when the engine is started. The increased crank time is the result of the time required to build high pressure in the fuel system before the engine starts.

Oil Pump Cold Start Rrrrp or Rasp

The oil pump design has changed from a gerotor gear type pump to a two speed vane type pump for fuel economy reasons. At temperatures of 32°F (0°C) or colder, when the engine has been sitting for a few hours it is possible to have air enter the pump through normal oil drainback. Upon startup the owner may hear a short Rrrrp or Rasp coming from the front of the engine. It is most often heard during a remote start. There is nothing wrong with the oil pump or oil system. No repairs should be attempted for this condition.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION