



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Aid: Unable to Perform BPP Relearn/Calibration

Models: 2004 Chevrolet Malibu, Malibu Maxx
equipped with 3.5L Engine (RPO LX9)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

After performing wiring repairs to or replacement of the Body Control Module (BCM) or Brake Pedal Position (BPP) sensor, a Technician may find that the Tech 2 will display "Device Control Not Allowed" when attempting to perform BPP Relearn/Calibration procedure.

Recommendation/Instructions

In order to properly perform the BPP Relearn/Calibration procedure, it will be necessary to first reprogram the PCM.

Warranty Information

For vehicles being serviced for Recall 13036, use the following labor operation – making sure to check the "Policy" flag when filing the warranty claim (2004 Malibu, Malibu Maxx with RPO LX9 Only) as well as reference PIC6041 in the comments section of the Job Card:

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION