

Service Bulletin

File in Section: 07 - Transmission/Transaxle

Bulletin No.: 02-07-30-029W

Date: June, 2014

INFORMATION

Subject: Product Quality Center (PQC) Assembly Replacement Process – For Dealers Required

to Contact PQC Prior to Replacing an Assembly

Models: 2015 and Prior GM Passenger Cars and Light Duty Trucks

Equipped with CNG, LPG or Gasoline Engine, Duramax® Diesel Engine, Automatic or

Manual Transmission and/or Transfer Case, Including Front Wheel Drive and Rear

Wheel Drive Vehicles

This bulletin has been revised to change Repair Order to Job Card, change the name of the PQC Cost Comparison Worksheet to Cost Comparison Worksheet for Assembly Repair vs Replacement and update the graphic showing the form and its location on GlobalConnect.

Please discard Corporate Bulletin Number 02-07-30-029V.

Service Agent Notification - Service Department Personnel Responsibility

Notice: Most Service Agents are not required to contact the PQC when REPAIRS are being made to the engine, transmission or transfer case assembly.

Notice: All Service Agents are still required to contact the PQC for any current restrictions or exchanges. For more information, see the section in this bulletin titled: Part Restriction and Exchange Program.

Notice: Service Agents that are required to contact the PQC for engine, transmission and/or transfer case assembly replacement authorization, will be notified by a GlobalConnect message and by their Regional Representative.

Notice: This bulletin only applies to Service Agents who are required to contact the PQC. Service Agents who are not required to contact the PQC, should refer to the latest version of Corporate Bulletin #12-07-30-001 for information on their Repair vs Replacement process.

Table of Contents

- Determining Whether to Call PQC
 - Part Restriction and Exchange Program
 - Customer Satisfaction
 - Service Agents Working With PCC (U.S. Only)

- PQC Process

- Before Calling PQC
- Cost Comparison Worksheet for Assembly Repair vs Replacement
- Calling PQC
- Global Warranty Management Transaction Submission — Record Retention — Assembly Return
 - Submitting Engine, Transmission or Transfer Case Transactions into Global Warranty Management (GWM)
 - Record Retention
 - Returning an Assembly to the Warranty Parts Center

Determining Whether to Call PQC

Service Agents can refer to Global Warranty
Management (GWM) and select the: "Items Not
Allowed" tab under: "Service Agent Profile" then
scroll right to view the date in order to determine if the
Service Agent is required to contact the PQC prior to
unit replacement involving the following Labor
Operations:

- 4067470 Partial Engine Replacement
- · 4067490 Engine Replacement
- 4067510 Engine Assembly Replacement
- 8464670 Transmission Replacement
- · 8441780 Transmission Replacement
- 8421160 Transfer Case Assembly Replacement
- ⇒ If Service Agents have any questions concerning why they are required to call the PQC for assembly replacement authorization they should contact their

- District Manager Aftersales (DMA), in Canada the District Manager-Customer Care and Service Process (DM-CCSP).
- ⇒ If Service Agents ARE required to contact the PQC, they MUST do so PRIOR to any assembly replacement and BEFORE submitting the above labor operations in GWM.

For more information on the PQC Process, see the PQC Process section in this Bulletin. For more information on submitting Transactions, see the Transaction Submission and Assembly Returns section in this Bulletin.

Part Restriction and Exchange Program

All Service Agents are still required to contact the PQC for the following components:

- Current parts restriction on the Allison transmission.
- Current parts restriction on the Duramax® diesel engine — RPO LGH or LML.
- · Any component listed in a current parts restriction.
- · A current assembly exchange program.

The Service Department Personnel should review the applicable documents related to the Part Restriction or Exchange Program and be prepared to provide diagnostic information.

Customer Satisfaction

There may be situations where an assembly can be repaired, but due to customer satisfaction reasons an assembly replacement should be considered. In these cases the service department personnel should review the concern with the District Manager Aftersales (DMA), in Canada the District Manager - Customer Care and Service Process (DM-CCSP).

For Service Agents required to contact the PQC, the service department personnel **MUST** be prepared to provide diagnostic information as well as a completed repair/replacement estimate portion of the Cost Comparison Worksheet for Assembly Repair vs Replacement. Service Agents required to contact the PQC, **MUST** advise the PQC when the DMA, in Canada the DM-CCSP authorizes the replacement of an engine, transmission or transfer case assembly for Customer Enthusiasm purposes versus repair.

Service Agents Working With PCC (United States Only)

All Service Agents that are working with the PCC to reimburse Independent Service Centers (ISC) must continue to follow the existing PCC processes.

PQC Process

Before Calling PQC

If diagnosis performed by the service department personnel indicates a need for an engine, transmission or transfer case assembly replacement, Service Agents required to call PQC must perform the following actions PRIOR to replacement and BEFORE contacting PQC:

- Complete the Calibration Verification Number process as outlined in the latest version of:
 - Corporate Bulletin #14-06-04-003: Identifying Non-GM ECM Calibration Use and Power-up Hardware Detection in Duramax Diesel Engines Using GDS 2
 - Corporate Bulletin #08-06-04-006 for Duramax® Diesel Engines
 - Corporate Bulletin #09-06-04-026 for Gasoline Engines / Transmissions
- For automatic transmissions only, perform a transmission cooler flush and record the code.
- The Condition and Cause including any diagnostic trouble codes (DTCs), symptoms, Scan Tool Snapshots and any other useful information observed and recorded by the technician. The technician must have detailed information required for proper root cause analysis and product concerns correction. This information is very valuable in ensuring that the replacement assemblies and current production parts help to continually improve our products.
- · Record the serial number of the failed assembly.
- Complete a Cost Comparison Worksheet for Assembly Repair vs Replacement. For help in locating this form, see the following section titled: Cost Comparison Worksheet for Assembly Repair vs Replacement On GlobalConnect (U.S.)
- Complete the Repair Estimate: Replacement
 Component Assembly Estimate: section for the
 assembly category included in the Cost
 Comparison Worksheet for Assembly Repair vs
 Replacement. Accurate repair versus replacement
 cost estimates (include the markups) are
 ESSENTIAL in order to eliminate a second call to
 the PQC.
- Have the Job Card number, VIN and the Service Agent BAC code ready when calling the PQC along with a detailed Customer Concern.

We are requesting that **ALL** service technicians use this opportunity to help GM better understand how and why a given component failed. For GM this is an opportunity to have direct and thorough feedback from the technician to provide to Engineering and thus improve the reliability and durability of both OEM and Genuine GM Parts assemblies.

Bulletin No.: 02-07-30-029W June, 2014 Page 3

Cost Comparison Worksheet for Assembly Repair vs Replacement On GlobalConnect (U.S.)

Transmission/Transaxle

Bulletin: Information for Dealers Not Required to Contact Product Quality Center for Driveline

(Transmission and Transfer Case) Replacement

 Bulletin
 12-07-30-001D

 Number
 11-00-89-005G

Form(s)

Cost Comparison Worksheet for Assembly Repair vs Replacement - This file can be saved to your PC. It is macro enabled to add the data entered into the Estimate Forms & will function with Microsoft Excel.

Cost Comparison Worksheet for Assembly Repair vs Replacement - This file can be saved to your PC & the forms can be printed then filled out.

Bulletin: Information for Dealers Required to Contact Product Quality Center for Driveline

(Transmission and Transfer Case) Replacement

Bulletin Number

02-07-30-029W

Form(s)

Cost Comparison Worksheet for Assembly Repair vs Replacement - This file can be saved to your PC. It is macro enabled to add the data entered into the Estimate Forms & will function with Microsoft Excel.

Cost Comparison Worksheet for Assembly Repair vs Replacement - This file can be saved to your PC & the forms can be printed then filled out.

Notice:

- To access the Cost Comparison Worksheet for Assembly Repair vs Replacement, Go to > GlobalConnect > Service Forms > Transmission/Transaxle > Bulletin 12-07-30-001 > Cost Comparison Worksheet for Assembly Repair vs Replacement.
- To access the Cost Comparison Worksheet for Assembly Repair vs Replacement, Go to > GlobalConnect > Service Forms > Engine/ Propulsion System > Bulletin 12-07-30-001 > Cost Comparison Worksheet for Assembly Repair vs Replacement.
- In Canada, Go to > GlobalConnect > Library >
 Service > Warranty Administration > Warranty
 Administration Home Page > Column Labeled
 Warranty Administration > Forms > Cost
 Comparison Worksheet for Assembly Repair vs
 Replacement. The Cost Comparison

Worksheet for Assembly Repair vs Replacement includes the following assembly categories: • Gas Engine Form • Diesel Engine Form • Automatic Transmission Form • Manual Transmission Form • Transfer Case PTU Form Each assembly category form has an integrated Repair Estimate: Replacement Component Assembly Estimate: worksheet that MUST be completed. -To access this form in the United States, go to GlobalConnect > Service Workbench > Service Forms > Transmission/Transaxle > select and download either of the two available forms. -To access this form in Canada, go to GlobalConnect > Library > Service > Warranty Administration > Warranty Administration Home Page > Column Labeled Warranty Administration > Forms > select

and download either of the two available forms.

Calling PQC Call the PQC at 1-866-654-7654 PRIOR to replacing the assembly. •

If the assembly replacement IS NOT authorized then proceed with repair of the assembly. If agreement on repairs cannot be reached, contact the DMA, in Canada the DM-CCSP for a final review of the case. • If the engine, transmission or transfer case assembly replacement IS authorized then proceed with the replacement. Be sure to include the PQC case number and to record the serial numbers of BOTH the failed component being removed and the replacement component being installed. Further calls to the PQC are not necessary and the Transaction can be submitted when ready. Once a determination to repair or replace has been made, further calls to the PQC are not necessary. The Transaction can be submitted when ready. Service Agents should not contact PQC to create a Pre-Authorization, as this is no longer part of the PQC Process. For details on how to submit Transactions, see the section titled "Transaction Submission and Assembly Returns" below.

Global Warranty Management Transaction Submission — Record Retention — Assembly Return

Submitting Engine, Transmission or Transfer Case Transactions into Global Warranty Management (GWM) Service Agents MUST complete all of the following Steps 1-6, in order to submit engine, transmission and/or transfer case Warranty Transactions into GWM: 1.

Scan the completed Job Card and attach it to the Warranty Transaction in GWM.

Notice: The Warranty Support Center requires that this action is performed on EVERY Warranty Transaction 2.

Scan the completed Repair Estimate: Replacement Component Assembly Estimate: worksheet of the Cost Comparison Worksheet for Assembly Repair vs Replacement and attach it to the Warranty Transaction in GWM. 3. When applicable insert the transmission flush code in the labor operation dependency field. 4. Enter the serial number of the new assembly into the: "Serial Number" field which will appear in the: "Parts Section" of the Transaction. 5.
Enter the serial number of the failed assembly into the: "Comment" field. 6.
Route for GM authorization (H route) all engine, transmission or transfer case replacement Warranty Transactions.

Record Retention All Service Agents are required to retain the completed Cost Comparison Worksheet for Assembly Repair vs Replacement. Attach the worksheet to the Job Card. On the Job Card, document the serial number of BOTH the failed assembly being removed and the replacement assembly being installed and transmission flush code as applicable. If applicable, attach the completed Calibration Verification Number (CVN) as applicable to the Job Card and place it in the Service Agent vehicle service history file.

Returning an Assembly to the Warranty Parts
Center Service Agents may be requested to return
the assembly to the Warranty Parts Center for
inspection. Failure to perform the following
procedures may result in a debit for the repair.
When returning an assembly the following MUST
BE ATTACHED to the return shipping container as
indicated by the instructions supplied with the new
assembly: 1.

A legible copy of the Job Card containing the serial number of BOTH the failed assembly being returned and the replacement assembly being installed. 2.

Document the transmission flush code (as applicable). 3.

A completed Calibration Verification Number (as applicable). 4.

A completed Cost Comparison Worksheet for Assembly Repair vs Replacement. •
All fluids MUST be drained and proper packaging procedures observed. •
If an engine assembly is being returned, the oil filter MUST be drained of oil, properly packaged and secured in a plastic bag and attached to the engine assembly. Duramax® is a Registered Trademark of General Motors LLC (United States) Duramax™ is a

Trademark of General Motors LLC