



Service Bulletin

PRELIMINARY INFORMATION

Subject: Intermittent No Start, Steering Column Lock Indicator On, Service Column Lock System Message, DTCs B2515, B305A Set

Models: 2010-2013 Cadillac SRX (Export Only)
Equipped with Steering Column Lock Control (RPO ULS)
and Built Prior to VIN Breakpoint BS561080

This PI has been revised to add model years and update the Recommendation/Instructions. Please discard PI0177.

Condition/Concern

Some customers may comment that the steering column lock indicator lamp is on and a service column lock system message is displayed in the DIC. The customer may also comment that they are unable to unlock the column and the vehicle will not start.

When checking the vehicle for DTCs, the body control module (BCM) may report B2515 or B305A stored in history or current.

Recommendation/Instructions (2010 Model Year)

First, confirm that the body control module (BCM) has the latest software. Replace the steering column and the steering column lock control module with the new part numbers listed below. Refer to the Steering Column Replacement and the Steering Column Lock Control Module Replacement procedures in SI.

Important: After the installation is complete, program and setup the steering column lock control module and center the steering angle sensor. Refer to the Steering Column Lock Control Module Programming and Setup and the Steering Angle Sensor Centering procedure in SI.

Recommendation/Instructions (2011-2012 Model Years)

First, confirm that the body control module (BCM) has the latest software. Replace the steering column lock control module with the new part number listed below. Refer to the Steering Column Lock Control Module Replacement procedure in SI.

Important: After the installation is complete, program and setup the steering column lock control module. Refer to the Steering Column Lock Control Module Programming and Setup.

Recommendation/Instructions (2013 Model Year)

First, confirm that the body control module (BCM) has the latest software. Reprogram the steering column lock control module (ESCL) using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the Steering Column Lock Control Module Programming and Setup.

Parts Information

Part Number	Description	Qty
12823254	Module, Steering Column Lock Control	1
11611150	Bolt, Steering Column Lock Control Module	2
22959839	Column, Steering	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7480068* 2010 Model Year Only	Steering Column Lock Control Module and Steering Column Replacement	2.1 hrs
7442420 2011-2012 Model Year	Steering Column Lock Control Module Replacement	Use Published Labor Operation Time
2810775 2013 Model Year	Steering Column Lock Control Module Reprogramming with SPS	Use Published Labor Operation Time
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION