



NUMBER: 08-091-14

GROUP: Electrical

DATE: October 24, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-086-13, DATED OCTOBER 30, 2013, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE THE ADDITION OF TIME ALLOWANCE REIMBURSABLE WITHIN THE PROVISIONS OF THE WARRANTY.**

SUBJECT:

Exterior Lamp Condensation And Fogging

OVERVIEW:

This bulletin involves evaluating lamp condensation and fogging condition.

DISCUSSION:

Some customers may report that on occasion, vehicle exterior lamp assemblies are fogged with a light layer of condensation on the inside of the lenses. This may be reported after the lamps have been turned on and brought up to operating temperature, turned off, and then rapidly cooled by cold water (such as rain, or the water from a car wash). Lens fogging can also occur under certain atmospheric conditions after a vehicle has been parked outside overnight (i.e., a warm humid day followed by clear cool night). This will usually clear as atmospheric conditions change to allow the condensation to change back into a vapor. Turning the lamps on will usually accelerate this process.

A lamp that exhibits condensation/fogging should be evaluated in a service bay environment by first drying all water from the outside surface of the lens and operating the lamp for 20 minutes.

If the condensation/fogging has begun to clear from the lamp lens after 20 minutes with the lamps operating, this indicates the lamp sealing has not been breached, and the lamp does not need to be replaced ([Fig. 1](#)).



Fig. 1 Condensation Fogging Do Not Replace

If the condensation/fogging has not begun to clear after 20 minutes with the lamps operating, or the lamp has large amounts of water droplets visible on most internal surfaces, this indicates an issue with the lamp sealing that has allowed water to enter the lamp. In this instance, the customer is also likely to report that moisture in the lamp is always present and never disappears. A lamp that exhibits internal moisture permanently should be replaced ([Fig. 2](#)).



Fig. 2 Heavy Water Droplets Replace

POLICY:

****Reimbursable within the provisions of the warranty.****

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-50-31-96	Housing, headlamp inspect for condensation (0 - Low Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
------	------------------